## LIEBHERR

## **CONSTRUCTION EQUIPMENT**

### **LIEBHERR L550 075036-1825 - Diesel Engine**

Sample No: LH0266827

Oil Type: PETRO CANADA DURON UHP 10W40

INFO	RMATIC	ON SUR L'ÉCHA	NTILLON	
Numéro d'échant.		LH0266827		 
Date d'échant.		20 Dec 2023		 
Heures de la Machine	Э	545		 
Heures de l'huile		0		 
Huile changée		Changed		 
Statut de l'echant.		NORMAL		 
<b>ETAT</b>	D'HUILE			
Visc 100°C	cSt	<b>11.9</b>		 
Oxydation (PA)	%	208		 
-4				
CONT	TAMINA	TION		
Eau	%	NEG		 
% de suie	%	00		 
Nitration (PA)	%	96		 
Sulfatation (PA)	%	111		 
Glycol	%	NEG		 
Essence	%	0 1.1		 
Silicium	ppm	○ 10		 
Sodium	ppm	O 2		 
Potassium	ppm	<b>3</b>		 
	la la	0 -		
(O)	AUX D'U	CURE		
me i	AUX D'U	SUKE		
Fer	ppm	<b>8</b>		 
Cuivre	ppm	<b>164</b>		 
Plomb	ppm	<b>8</b>		 
Étain	ppm	<b>1</b>		 
Aluminium	ppm	<b>3</b>		 
Chrome	ppm	<b>○</b> <1		 
Molybdène	ppm	<b>46</b>		 
Nickel	ppm	<b>○</b> <1		 
Titane	ppm	0		 
Argent	ppm	<b>0</b>		 
Manganèse	ppm	<b>()</b> <1		 
Vanadium	ppm	0		 



Sintra Inc. (division Ouest)

9975 rue de Chateauneuf, Local B Brossard, QC

CA J4Z 3V6

Contact: Service Manager jonathan.smith@sintra.ca

T: F:

#### Diagnostic

The oil change at the time of sampling has been noted. Confirm the source of the lubricant being utilized for top-up/fill. Resample at the next service interval to monitor. No other corrective action is recommended at this time.Metal levels are typical for a new component breaking in. Light fuel dilution occurring. No other contaminants were detected in the oil. Additive levels indicate the addition of a different brand, or type of oil. The condition of the oil is acceptable for the time in service.

Depot:SINBROUnique No:5736002Signed:Kevin MarsonReport Date:04 Mar 2024

1364

824

705

45 88

920

**ADDITIFS** 

ppm

ppm

ppm

ppm

ppm

ppm

Calcium

Zinc

Magnésium

Phosphore

Baryum

Bore

# LIEBHERR







#### **GRAPHS**

