

PROBLEM SUMMARY

Sample Rating Trend

GLYCOL






913075


Component

Diesel Engine

PETRO CANADA DURON SHP 15W40 (--- GAL)

COMPONENT CONDITION SUMMARY





RECOMMENDATION

We advise that you check for the source of the coolant leak. Check for low coolant level. We recommend an early resample to monitor this condition.

PROBLEMATIC TEST RESULTS								
Sample Status				ABNORMAL	ABNORMAL	NORMAL		
Aluminum	ppm	ASTM D5185m	>20	△ 31	▲ 31	49		
Sodium	ppm	ASTM D5185m		446	3	13		

Customer Id: GFL415 Sample No.: GFL0105585 Lab Number: 06032239 Test Package: FLEET



To manage this report scan the QR code

To discuss the diagnosis or test data: Jonathan Hester +1 919-379-4092 x4092 jhester@wearcheckusa.com

To change component or sample information: Customer Service +1 1-800-237-1369 customerservice@wearcheck.com

RECOMMENDED ACTIONS

Action	Status	Date	Done By	Description
Resample			?	We recommend an early resample to monitor this condition.
Check Glycol Access			?	We advise that you check for the source of the coolant leak.

HISTORICAL DIAGNOSIS

16 Nov 2023 Diag: Don Baldridge

WEAR



No corrective action is recommended at this time. Resample at the next service interval to monitor. The aluminum level is abnormal. All other component wear rates are normal. There is no indication of any contamination in the oil. The BN result indicates that there is suitable alkalinity remaining in the oil. The condition of the oil is suitable for further service.



27 Apr 2023 Diag: Doug Bogart

NORMAL



Oil and filter change at the time of sampling has been noted. Resample at the next service interval to monitor. All component wear rates are normal. Elevated aluminum (Al) and/or lead (Pb) and potassium (K) levels in your metals analysis are likely a result of solder flux release into the lubricant and is common on new equipment/components. Test for glycol is negative. The BN result indicates that there is suitable alkalinity remaining in the oil. The condition of the oil is suitable for further service.



02 Feb 2023 Diag: Sean Felton

NORMAL




Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the oil. The BN result indicates that there is suitable alkalinity remaining in the oil. The condition of the oil is suitable for further service.





OIL ANALYSIS REPORT





Machine Id 913075 Component **Diesel Engine**

PETRO CANADA DURON SHP 15W40 (--- GAL)

DIAGNOSIS

Recommendation

We advise that you check for the source of the coolant leak. Check for low coolant level. We recommend an early resample to monitor this condition.

Wear

The aluminum level is abnormal. All other component wear rates are normal.

Contamination

Sodium and/or potassium levels are high.

▲ Fluid Condition


The BN result indicates that there is suitable alkalinity remaining in the oil.


N SHP 15W40 (- GAL)	Feb 202	3 Apr2023	Nov2023 D	ec2023	
SAMPLE INFOR	MATION	method	limit/base	current	history1	history2
Sample Number		Client Info		GFL0105585	GFL0101533	GFL0081395
Sample Date		Client Info		08 Dec 2023	16 Nov 2023	27 Apr 2023
Machine Age	hrs	Client Info		3504	3504	1894
Oil Age	hrs	Client Info		3504	1894	1248
Oil Changed		Client Info		Not Changd	N/A	Changed
Sample Status				ABNORMAL	ABNORMAL	NORMAL
CONTAMINAT	ION	method	limit/base	current	history1	history2
Fuel		WC Method	>3.0	<1.0	<1.0	<1.0
Water		WC Method	>0.2	NEG	NEG	NEG
WEAR METAL	S	method	limit/base	current	history1	history2
ron	ppm	ASTM D5185m	>90	52	43	64
Chromium	ppm	ASTM D5185m	>20	2	1	2
Nickel	ppm	ASTM D5185m	>2	4	5	0
Γitanium	ppm	ASTM D5185m	>2	0	<1	0
Silver	ppm	ASTM D5185m	>2	<1	<1	0
Aluminum	ppm	ASTM D5185m	>20	<u></u> 31	△ 31	49
_ead	ppm	ASTM D5185m	>40	0	0	0
Copper	ppm	ASTM D5185m	>330	7	8	3
 Γin	ppm	ASTM D5185m	>15	1	1	0
/anadium	ppm	ASTM D5185m		0	0	0
Cadmium	ppm	ASTM D5185m		0	0	0
ADDITIVES		method	limit/base	current	history1	history2
Boron	ppm	ASTM D5185m	0	13	0	0
Barium	ppm	ASTM D5185m	0	0	0	0
Molybdenum	ppm	ASTM D5185m	60	75	62	63
Manganese	ppm	ASTM D5185m	0	1	<1	1
Magnesium	ppm	ASTM D5185m	1010	959	899	1030
Calcium	ppm	ASTM D5185m	1070	1077	1073	1180
Phosphorus	ppm	ASTM D5185m	1150	1058	949	1059
Zinc	ppm	ASTM D5185m	1270	1329	1192	1347
Sulfur	ppm	ASTM D5185m	2060	2633	2432	3251
CONTAMINAN	ITS	method	limit/base	current	history1	history2
Silicon	ppm	ASTM D5185m	>25	17	10	7
Sodium	ppm	ASTM D5185m		446	3	13
Potassium	ppm	ASTM D5185m	>20	6	3	104
Glycol	%	*ASTM D2982		NEG	NEG	NEG
INFRA-RED		method	limit/base	current	history1	history2
Soot %	%	*ASTM D7844	>6	1.6	1.4	1.3
Vitration	Abs/cm	*ASTM D7624	>20	12.6	10.2	11.8
Sulfation	Abs/.1mm	*ASTM D7415	>30	24.5	23.8	21.9
FLUID DEGRAI	OATION	method	limit/base	current	history1	history2
Oxidation	Abs/.1mm	*ASTM D7414	>25	20.3	19.2	19.7
	mg KOH/g	ASTM D2896				
Base Number (BN)	IIIQ NOT/u	ASTIVI DZOSD	9.8	6.9	5.5	5.3


Submitted By: Frank Wolak





OIL ANALYSIS REPORT















FLUID PHOP	ELLIES	memod	IIIIII/Dase	Current	HISTORY	HISTORY
Visc @ 100°C	cSt	ASTM D445	15.4	14.0	14.1	13.4

GRAPHS













Certificate L2367

Laboratory Sample No. Lab Number **Unique Number**

: WearCheck USA - 501 Madison Ave., Cary, NC 27513

: GFL0105585 : 06032239 : 10782030

Recieved Diagnosed Diagnostician

: 12 Dec 2023 : 15 Dec 2023 : Jonathan Hester

Test Package : FLEET (Additional Tests: Glycol)

To discuss this sample report, contact Customer Service at 1-800-237-1369. * - Denotes test methods that are outside of the ISO 17025 scope of accreditation. GFL Environmental - 415 - Michigan East

6200 Elmridge Sterling Heights, MI US 48313 Contact: Frank Wolak fwolak@gflenv.com T: (586)825-9514

Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012)