# CONSTRUCTION EQUIPMENT 158596 VOLVO A25E 73627 - COOLANT



WC203701 Sample No: **Oil Type:** EXTENDED LIFE COOLANT Job No: 158596

VOLVO

## 

Sample Number	
Sample Date	
Machine Hours	
Sample Status	

SAMPLE INFURMATION		
ple Number	WC203701	
ple Date	01 Mar 2018	
hine Hours	12275	
ple Status	NORMAL	

COOLANT CONDITION				
Boron	ppm	54		 
Phosphorus	ppm	<b>□</b> <1		 
Sodium	ppm	2419		 
Potassium	ppm	228		 
Silicon	ppm	29		 
рН	Scale 0-14	8.18		 
Reserve Alkalinity	Scale 0-20	3.6		 
Molybdenum	ppm	<b>□</b> <1		 
Nitrites	ppm	520		 
Percentage Glycol	%	50.0		 
Freezing Point	°C	<b>-37</b>		 

## CONTAMINATION

Magnesium	ppm	3	 	
Calcium	ppm	20	 	
Coolant Appeara	nce	Cloudy	 	
Coolant Color		Orange	 	
Sand/Dirt	scalar		 	
Debris	scalar		 	
Precipitate	scalar		 	
Silt	scalar		 	
CORRO	SION			
Iron	ppm	0	 	

Iron	ppm	0			
Aluminum	ppm	0			
Copper Lead	ppm	0			
Lead	ppm	<b>  </b> <1			
Tin	ppm	0			



#### **STRONGCO INC**

1730 RUE DE L'HYDRO VAL D`OR, QC CA J9P 6Z2 Contact: Pierre Gauthier pgauthier@strongco.com T: F: (819)825-1360

#### Diagnosis

We recommend that you drain the system and refill with a 50/50 longlife coolant/water mixture. Resample at the next service interval to monitor.All metal levels are normal indicating no corrosion in the cooling system. There is no indication of any contamination in the coolant. The coolant is cloudy indicating either an overconcentration of coolant additives, or a mixing of incompatible coolant technologies. The nitrite level is acceptable. The pH level of this fluid is within the acceptable limits. The reserve alkalinity of this fluid is acceptable.

Depot:	VOLVO0229
Unique No:	4718067
Signed:	Kevin Marson
Report Date:	09 Jul 2018


## **CONSTRUCTION EQUIPMENT**



# GRAPHS

#### Iron/Tin/Silver

VOLVO



Report Id: VOLVO0229 [WCAMIS] 02226918 (Generated: 09/28/2023 15:36:58) Rev: 1

Contact/Location: Pierre Gauthier - VOLVO0229

Mar1/18

Mar1/18

Mar1/18