

CONSTRUCTION EQUIPMENT VOLVO ECR235CL 110174 - PUMP



Sample No:VC464435Oil Type:{unknown}

Job No:

Boron

	E INFORMATION	N		
Sample Number	-	VC464435	 	
Sample Date		08 Mar 2010	 	
Machine Hours		1058	 	
Oil Hours		1058	 	
Oil Changed		Not Changd	 	
Sample Status		NORMAL	 	
OIL CON	DITION			
Visc @ 40°C	cSt	43.33	 	
VOLVO			 	
	MINATION			
Silicon	ppm	■4	 	
Sodium	ppm	■ <1	 	
Potassium	ppm	2	 	
VOLVO				
WEAR N	METALS			
Iron	ppm	4	 	
Copper	ppm	18	 	
Lead	ppm	 <1	 	
Tin	ppm	0	 	
Aluminum	ppm	2	 	
Chromium	ppm		 	
Molybdenum	ppm	<1	 	
Nickel	ppm	■ <1	 	
Titanium	ppm	0	 	
Silver	ppm	0	 	
Manganese	ppm	<1	 	
Vanadium	ppm	0	 	
	VES			
Calcium	ppm	100	 	
Magnesium	ppm	2	 	
Zinc	ppm	581	 	
Phosphorus	ppm	470	 	
Barium	ppm	<1	 	
D				



DAYTON CONSTRUCTION 146 BUNKER HILL ROAD

WATERTOWN, CT US 06795 Contact: SERVICE MANAGER

T: (860)274-2998 F:

Diagnosis

Resample at the next service interval to monitor.All component wear rates are normal. There is no indication of any contamination in the component. The condition of the oil is acceptable for the time in service.

Depot:DAYWATUnique No:5144086Signed:Don BaldridgeReport Date:26 Mar 2010

<1


ppm

CONSTRUCTION EQUIPMENT



GRAPHS

VOLVO



Report Id: DAYWAT [WUSCAR] 02599156 (Generated: 07/06/2023 09:31:24) Rev: 1

Contact/Location: SERVICE MANAGER - DAYWAT