
CONSTRUCTION EQUIPMENT 327210 VOLVO EC480E 314662 - LEFT SWING DRIVE




VOLVO

Job No:

327210





ADDITIVES

Calcium	ppm	5	 	
Magnesium	ppm	□ <1	 	
Zinc	ppm	25	 	
Phosphorus	ppm	311	 	
Barium	ppm	6	 	
Boron	ppm	3	 	



STRONGCO EQUIPMENT-EDMONTON

25616 117 Ave NW Acheson, AB CA T7X 6C2 Contact: Jonathan Morton jmorton@strongco.com T: (780)464-1909 F: (780)464-0434

Diagnosis

Confirm the source of the lubricant being utilized for top-up/fill. Resample at the next service interval to monitor.All component wear rates are normal. There is no indication of any contamination in the oil. Additive levels indicate the addition of a different brand, or type of oil. The condition of the oil is acceptable for the time in service.

 Depot:
 VOLVO3908

 Unique No:
 5421778

 Signed:
 Kevin Marson


 Report Date:
 24 Jun 2022

CONSTRUCTION EQUIPMENT



GRAPHS

VOLVO



Report Id: VOLVO3908 [WCAMIS] 02496818 (Generated: 09/28/2023 10:12:27) Rev: 1

Contact/Location: Jonathan Morton - VOLVO3908