

CONSTRUCTION EQUIPMENT CARGILL 389044 VOLVO L120H 16705 - FRONT AXLE



Sample No: VCP392408
Oil Type: VOLVO WB 102

Job No: 389044

VOLVO				
	INFORMATION			
Sample Number		VCP392408	VCP334096	
Sample Date		27 Dec 2023	21 Oct 2022	
Machine Hours		2906	1294	
Oil Hours		0	294	
Oil Changed		Not Changd	Not Changd	
Sample Status		NORMAL	NORMAL	
OIL CON	DITION			
Visc @ 40°C	cSt	51.0	54.0	
Visc & To C	CSt		3 1.0	
VOLVO				
CONTAN	MOITANIN			
Water	%	NEG	NEG	
Silicon	ppm	5	9	
Sodium	ppm	2	2	
Potassium	ppm	-<1	< 1	
WEAR N	AETALS			
	JE I VEZ			
Iron	ppm	■ 54	4 1	
Copper	ppm	■ <1	- <1	
Lead	ppm	■0	- <1	
Tin	ppm	■0	0	
Aluminum	ppm	1	- <1	
Chromium	ppm	■1	1	
Molybdenum	ppm	■ <1	1	
Nickel	ppm	■ <1	- <1	
Titanium	ppm	0	<1	
Silver	ppm	0	0	
Manganese	ppm	2	4	
Vanadium	ppm	0	0	
ADDITIV	VES			
Calcium	ppm	2809	3120	
Magnesium	ppm	6	11	
Zinc	ppm	1250	1264	
Phosphorus	ppm	1045	1121	
Barium	ppm	0	0	
Boron	ppm	15	17	
_ 5. 5	PP.11			



STRONGCO EQUIPMENT-EDMONTON

25616 117 Ave NW Acheson, AB CA T7X 6C2 Contact: Jonathan Morton jmorton@strongco.com T: (780)464-1909 F: (780)464-0434

Diagnosis

Confirm the source of the lubricant being utilized for top-up/fill. Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the oil. Additive levels indicate the addition of a different brand, or type of oil. The condition of the oil is acceptable for the time in service.

Depot:VOLVO3908Unique No:5708332Signed:Kevin MarsonReport Date:09 Jan 2024



CONSTRUCTION EQUIPMENT





