



CONSTRUCTION EQUIPMENT

VOLVO L110H 631301 - COOLANT



Sample No: VCP274970
Oil Type: VOLVO COOLANT VCS (YELLOW)
Job No:



SAMPLE INFORMATION

| | | | | |
|---------------|-------------|-----|-----|-----|
| Sample Number | VCP274970 | --- | --- | --- |
| Sample Date | 03 May 2020 | --- | --- | --- |
| Machine Hours | 11442 | --- | --- | --- |
| Sample Status | NORMAL | --- | --- | --- |

COVANTA
 350 FLAKENBURG ROAD
 TAMPA, FL
 US 33619
 Contact: SERVICE MANAGER



COOLANT CONDITION

| | | | | | |
|--------------------|------------|--------|-----|-----|-----|
| pH | Scale 0-14 | ■ 7.96 | --- | --- | --- |
| Reserve Alkalinity | Scale 0-20 | --- | --- | --- | --- |
| Nitrites | ppm | ■ 0 | --- | --- | --- |
| Percentage Glycol | % | ■ 50 | --- | --- | --- |
| Freezing Point | °C | ■ -38 | --- | --- | --- |

T: (813)684-5688
 F:



CONTAMINATION

| | | | | |
|--------------------|--------|-----|-----|-----|
| Coolant Appearance | normal | --- | --- | --- |
| Coolant Color | Yllow | --- | --- | --- |

Diagnosis

The fluid is suitable for further service. There is no indication of any contamination in the coolant. The carboxylate level of this fluid is acceptable. The glycol level is acceptable. The pH level of this fluid is within the acceptable limits.

Depot: COVTAM
Unique No: 9025312
Signed: Doug Bogart
Report Date: 14 May 2020




CONSTRUCTION EQUIPMENT




GRAPHS


Iron/Tin/Silver




Reserve Alkalinity



Copper/Aluminum/Lead



Freeze Point



pH



Nitrites

