

CONSTRUCTION EQUIPMENT 5586 VOLVO EC46OCL 110437 - RIGHT SWING DRIVE



Sample No: VCP301207

Oil Type: VOLVO PREMIUM GEAR OIL 85W-140 GL-5

Job No: 5586

ZAMPI F	INFORMATIO	N		
	. IINI UNITATIOI	VCP301207	VCP181447	
Sample Number				
Sample Date		06 Jan 2021	15 Dec 2015	
Machine Hours		6082	4194	
Oil Hours		0	0	
Oil Changed		Changed	Changed	
Sample Status		ABNORMAL	ABNORMAL	
VOLVO				
OIL CON	DITION			
Visc @ 40°C	cSt	□305	274.9	
		_	_	
VOLVO	AIN A TION			
_	MINATION			
Water	%	△ 0.292	△ 0.422	
Silicon	ppm	6	1 4	
Sodium	ppm	2	2	
Potassium	ppm	■<1	6	
WEAR M	AFTAI S			
_		=160	= 200	
Iron	ppm	168	□ 288	
Copper	ppm	9	20	
Lead	ppm	 <1	0	
Tin	ppm	<1	0	
Aluminum	ppm	0	3	
Chromium	ppm	2	4	
Molybdenum	ppm	1	0	
Nickel	ppm	<1	<1	
Titanium	ppm	<1	<1	
Silver	ppm	<1	0	
Manganese	ppm	2	4	
Vanadium	ppm	0	0	
VOLVO				
ADDITIV	/ES			
Calcium	ppm	□ 52	□35	
Magnesium	ppm	1 5	5	
Zinc	ppm	■ 68	1 73	
Phosphorus	ppm	■ 812	807	
Barium	ppm	0	<1 < 1	
Boron		■83	68	
DOTOTI	ppm	0 3	00	



MCCLUNG-LOGAN EQUIPMENT CO - RICHMOND
1345 MOUNTAIN ROAD
GLEN ALLEN, VA
US 23060
Contact: KYLE RATLIFFE
KRATLIFFE@MCCLUNG-LOGAN.COM
T:
F: (804)266-1611

Diagnosis

The oil change at the time of sampling has been noted. Resample at the next service interval to monitor. Please note that this is a corrected copy for laboratory data updates. All component wear rates are normal. There is a light concentration of water present in the oil. The condition of the oil is acceptable for the time in service.

Depot:VOLVO8882Unique No:9313206Signed:Jonathan HesterReport Date:12 Jan 2021



CONSTRUCTION EQUIPMENT





