

CONSTRUCTION EQUIPMENT 127242 VOLVO A60H 340053 - BRAKE



Sample No: VCP309343
Oil Type: NOT GIVEN
Job No: 127242

SAMPLE	INFORMATION				
Sample Number		VCP309343	VCP302359	VCP271868	
Sample Date		17 May 2021	06 Mar 2021	05 Aug 2020	
Machine Hours		4220	3845	3000	
Oil Hours		0	0	0	
Oil Changed		Not Changd	Changed	Not Changd	
Sample Status		ABNORMAL	ABNORMAL	ABNORMAL	
OIL CON	DITION				
/isc @ 40°C	cSt	45.7	43.2	42.8	
VOLVO					
CONTAN	MINATION				
ilicon	ppm	1 9	2 5	1 8	
Sodium	ppm	4	5	3	
otassium	ppm	■<1	0	- <1	
WEAR M	IETALS				
ron	ppm	57	6 9	■49	
Copper	ppm	<u></u> 164	232	<u>^</u> 231	
ead	ppm	2	3	1	
in	ppm	■ <1	0	□0	
Aluminum	ppm	2	2	0	
Chromium	ppm	■ <1	- <1	- <1	
Molybdenum	ppm	2	<1	1	
lickel	ppm	■3	4	4	
itanium	ppm	<1	<1	<1	
ilver	ppm	<1	0	0	
Manganese	ppm	1	2	2	
/anadium	ppm	<1	0	0	
VOLVO					
ADDITIV	IES				
Calcium	ppm	3026	3355	3298	
Magnesium	ppm	14	8	10	
Zinc	ppm	1203	1347	1310	
Phosphorus	ppm	1064	1098	1120	
Barium	ppm	0	0	0	
Boron	ppm	66	77	98	

ROMCO INC - AUSTIN BRANCH

1150 WEST OLD SETTLERS BOULEVARD ROUNDROCK, TX US 78681 Contact: MATT MACHANN mmachann@romco.com T: (832)270-0121 F: (512)845-7565

Diagnosis

No corrective action is recommended at this time. Resample at the next service interval to monitor. The copper level is abnormal. All other component wear rates are normal. There is no indication of any contamination in the fluid. The condition of the fluid is acceptable for the time in service.

Depot:VOLVO0088Unique No:9517528Signed:Don BaldridgeReport Date:27 May 2021



CONSTRUCTION EQUIPMENT





