



CONSTRUCTION EQUIPMENT

VOLVO A40G 352512 - BRAKE COOLING SYSTEM



Sample No: VCP313717
Oil Type: VOLVO WB 102
Job No:



ALTA EQUIPMENT/FLAGLER CONSTRUCTION EQUIPMENT LLC
 8418 PALM RIVER ROAD
 TAMPA, FL
 US 33619
 Contact: BILL PYLES
 wpyles@altaequipfl.com
 T: (407)375-5788
 F: (813)630-2233



SAMPLE INFORMATION

Sample Number	VCP313717	---	---	---
Sample Date	03 Jun 2021	---	---	---
Machine Hours	1089	---	---	---
Oil Hours	1089	---	---	---
Oil Changed	Not Chngd	---	---	---
Sample Status	ABNORMAL	---	---	---



OIL CONDITION

Visc @ 40°C	cSt	■ 39.9	---	---	---
-------------	-----	--------	-----	-----	-----



CONTAMINATION

Water	%	NEG	---	---	---
Silicon	ppm	■ 6	---	---	---
Sodium	ppm	■ 2	---	---	---
Potassium	ppm	■ <1	---	---	---



WEAR METALS

Iron	ppm	▲ 119	---	---	---
Copper	ppm	■ 2	---	---	---
Lead	ppm	■ 0	---	---	---
Tin	ppm	■ 0	---	---	---
Aluminum	ppm	■ 0	---	---	---
Chromium	ppm	■ 3	---	---	---
Molybdenum	ppm	■ 1	---	---	---
Nickel	ppm	■ <1	---	---	---
Titanium	ppm	0	---	---	---
Silver	ppm	0	---	---	---
Manganese	ppm	■ 4	---	---	---
Vanadium	ppm	0	---	---	---



ADDITIVES

Calcium	ppm	■ 133	---	---	---
Magnesium	ppm	■ 1	---	---	---
Zinc	ppm	■ 39	---	---	---
Phosphorus	ppm	■ 1421	---	---	---
Barium	ppm	■ 0	---	---	---
Boron	ppm	■ 313	---	---	---

Diagnosis

No corrective action is recommended at this time. Resample at the next service interval to monitor. The iron level is abnormal. All other component wear rates are normal. There is no indication of any contamination in the fluid. The condition of the fluid is acceptable for the time in service.

Depot: VOLVO0093
Unique No: 9565490
Signed: Jonathan Hester
Report Date: 01 Jul 2021



CONSTRUCTION EQUIPMENT



GRAPHS

