

CONSTRUCTION EQUIPMENT VOLVO EC160EL 310364 - SWING DRIVE



Sample No: VCP384763

Oil Type: CHEVRON MULTIGEAR EP5 80W90

Report Id: DHFCOL [WUSCAR] 05877266 (Generated: 08/10/2023 11:42:16) Rev: 1

Job No:

VOLVO CAMPI F	INFORMATION	ı			
	. IIMI OMMATIOI		VCD2250.47	<u> </u>	
Sample Number		VCP384763	VCP335947		
Sample Date		13 Jun 2023	25 Mar 2022		
Machine Hours		4000	3000		
Oil Hours		1000	1000		
Oil Changed		Changed	Changed		
Sample Status		NORMAL	NORMAL		
VOLVO					
OIL CON	DITION				
Visc @ 40°C	cSt	126	1 19		
V13C @ 40 C	CSt	120			
VOLVO					
CONTAN	INATION				
Silicon	ppm	9	1 4		
Sodium	ppm	■ 0	0		
Potassium	ppm	■<1	- <1		
	1.1.	_	_		
VOLVO					
WEAR M	1ETALS				
Iron	ppm	■ 59	■91		
Copper	ppm	2	4		
Lead	ppm	0	0		
Tin	ppm	■ 0	<1		
Aluminum	ppm	1	3		
Chromium	ppm	■<1	<1		
Molybdenum	ppm	4	4		
Nickel	ppm	■ 0	0		
Titanium	ppm	1	2		
Silver	ppm	0	<1		
Manganese	ppm	□ <1	- <1		
Vanadium	ppm	<1	0		
VOLVO	IFC				
ADDITIV	E				
Calcium	ppm	■98	220		
Magnesium	ppm	■ 35	9 5		
Zinc	ppm	59	125		
Phosphorus	ppm	941	1 021		
Barium	ppm	■ 0	0		
Boron	ppm	184	164		



DH FUNK AND SONS LLC 3995 CONTINENTAL DRIVE COLUMBIA, PA US 17512 Contact: GARY SHEPHERD GSHEPHERD@DHFUNK.COM T:

F:

Diagnosis

Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.

Depot:DHFCOLUnique No:10522369Signed:Sean FeltonReport Date:20 Jun 2023

Page 1 of 2



CONSTRUCTION EQUIPMENT





