

CONSTRUCTION EQUIPMENT 9391 VOLVO A30G 740290 - WET DISC BRAKE



Sample No: VCP424589
Oil Type: NOT GIVEN

Job No: 9391

SAMPLE	INFORMATION			
Sample Number	_	VCP424589	 	
Sample Date		02 Aug 2023	 	
Machine Hours		8505	 	
Oil Hours		0	 	
Oil Changed		Not Changd	 	
Sample Status		ABNORMAL	 	
OIL CON	NITION			
Visc @ 40°C	cSt	45.0	 	
VOLVO				
CONTAN	MINATION			
Water	%	<u></u>	 	
Silicon	ppm	23	 	
Sodium	ppm	5	 	
Potassium	ppm	1	 	
	le le			
VOLVO	ACTAL C			
WEAR N	NE I ALS			
Iron	ppm	<u></u> ▲ 63	 	
Copper	ppm	■77	 	
Lead	ppm	■ <1	 	
Tin	ppm	■<1	 	
Aluminum	ppm	■3	 	
Chromium	ppm	■<1	 	
Molybdenum	ppm	0	 	
Nickel	ppm	■ <1	 	
Titanium	ppm	0	 	
Silver	ppm	0	 	
Manganese	ppm	1	 	
Vanadium	ppm	<1	 	
VOLVO			 	
ADDITIV	/ES			
Calcium	ppm	3581	 	
Magnesium	ppm	14	 	
Zinc	ppm	1413	 	
Phosphorus	ppm	1270	 	
Barium	ppm	0	 	
Boron	ppm	133	 	

Report Id: VOLVO0264 [WUSCAR] 05930531 (Generated: 08/23/2023 15:47:53) Rev: 1



McClung-Logan Virginia LLC 4112 HOLLAND BLVD CHESAPEAKE, VA US 23323 Contact: TOMMY GRIFFIN tgriffin@mcclung-logan.com T: (757)485-3314 F: (757)485-3415

Diagnosis

No corrective action is recommended at this time. Resample at the next service interval to monitor. The iron level is abnormal. There is a light concentration of water present in the oil. The condition of the oil is acceptable for the time in service.

Depot:VOLVO0264Unique No:10615802Signed:Don BaldridgeReport Date:23 Aug 2023



CONSTRUCTION EQUIPMENT





