

CONSTRUCTION EQUIPMENT

GOLF RENTAL DEUTZ NOT GIVEN VCP40 1 174 (S/N NO INFO ON SIF/BOTTLE) - DIESEL ENGINE

Sample No: VCP401174

Oil Type: DIESEL ENGINE OIL SAE 15W40

Job No: GOLF RENTAL

VOLVO				
SAMPLE II	NFORMATION			
Sample Number	-	VCP401174	 	
Sample Date		11 Sep 2023	 	
Machine Hours		0	 	
Oil Hours		0	 	
Oil Changed		Changed	 	
Sample Status		ABNORMAL	 	
VOLVO	TION			
OIL CONDI	TION			
Visc @ 100°C	cSt	15.4	 	
Base Number (BN)	mg KOH/g	■9.9	 	
Oxidation (PA)	%	91	 	
VOLVO	IATION			
CONTAMIN	NATIUN			
Soot %	%	0.2	 	
Nitration (PA)	%	86	 	
Sulfation (PA)	%	63	 	
Glycol	%	NEG	 	
Fuel	%	<1.0	 	
Silicon	ppm	△ 50	 	
Sodium	ppm	6	 	
Potassium	ppm	4	 	
VOLVO	TALC			
WEAR ME	I ALS			
Iron	ppm	43	 	
Copper	ppm	■30	 	
Lead	ppm	■ <1	 	
Tin	ppm	■ <1	 	
Aluminum	ppm	43	 	
Chromium	ppm	2	 	
Molybdenum	ppm	60	 	
Nickel	ppm	2	 	
Titanium	ppm	■ <1	 	
Silver	ppm	0	 	
Manganese	ppm	2	 	
Vanadium	ppm	<1	 	
VOLVO				
ADDITIVE:	7			
Calcium	ppm	1759	 	
Magnesium	ppm	1033	 	
Zinc	ppm	1533	 	
Phosphorus	ppm	1179	 	
Barium	ppm	■0	 	
Boron	ppm	12	 	
	1.5			

ALTA EQUIPMENT COMPANY

5151 DR MARTIN LUTHER KING BLVD FORT MYERS, FL US 33905

Contact: DEWAYNE BEARD DBeard@flaglerce.com T: (239)481-8554

F: (239)481-3302

Diagnosis

We advise that you check the air filter, air induction system, and any areas where dirt may enter the component. The oil change at the time of sampling has been noted. Resample at the next service interval to monitor.All component wear rates are normal. Elemental levels of silicon (Si) and aluminum (Al) indicate alumina-silicate (coarse dirt) ingress. The BN result indicates that there is suitable alkalinity remaining in the oil. The condition of the oil is acceptable for the time in service.

Depot:VOLVO0090Unique No:10649645Signed:Don BaldridgeReport Date:20 Sep 2023



CONSTRUCTION EQUIPMENT





