

CONSTRUCTION EQUIPMENT VOLVO L90H 625060 - HYDRAULIC SYSTEM



Sample No: VCP411992

Oil Type: VOLVO SUPER HYDRAULIC OIL 46

Job No:

| VOLVO | | | | |
|---------------------|------------|---------------|----------------|------|
| SAMPLE II | NFORMATION | | | |
| Sample Number | - | VCP411992 | VCP301598 | |
| Sample Date | | 25 Aug 2023 | 11 Feb 2021 | |
| Machine Hours | | 2836 | 914 | |
| Oil Hours | | 0 | 914 | |
| Oil Changed | | Not Changd | Not Changd | |
| Sample Status | | ABNORMAL | ABNORMAL | |
| | | | | |
| OIL CONDI | TION | | | |
| Visc @ 40°C | cSt | 42.2 | □ 43.7 | |
| Acid Number (AN) | | 0.31 | 0.320 | |
| Acid Nulliber (AIV) | mg kon/g | 0.31 | 0.320 | |
| VOLVO | INTION . | | | |
| CONTAMIN | NATION | | | |
| Particles >4µm | | <u> </u> | <u>▲</u> 11162 | |
| Particles >6µm | | △ 3579 | □ 1247 | |
| Particles >14µm | | <u> </u> | 6 2 | |
| ISO 4406:1999 (c) | | 21/19/15 | 21/17/13 | |
| Silicon | ppm | ■4 | ■3 | |
| Sodium | ppm | ■ 3 | 0 | |
| Potassium | ppm | ■0 | < 1 | |
| VOLVO | | | | |
| WEAR ME | TALS | | | |
| Iron | ppm | 9 | 4 | |
| Copper | ppm | 2 | 2 | |
| Lead | ppm | 1 | 2 | |
| Tin | ppm | ■0 | - <1 | |
| Aluminum | ppm | □ 0 | 0 | |
| Chromium | ppm | ■<1 | - <1 | |
| Molybdenum | ppm | □ 0 | - <1 | |
| Nickel | ppm | ■0 | 0 | |
| Titanium | ppm | 0 | 0 | |
| Silver | ppm | 0 | 0 | |
| Manganese | ppm | | - <1 | |
| Vanadium | ppm | 0 | 0 | |
| VOLVO | | | | |
| ADDITIVE: | | | | |
| Calcium | ppm | 160 | 162 | |
| Magnesium | ppm | 4 | 3 | |
| Zinc | ppm | 449 | 458 | |
| Phosphorus | ppm | 244 | 367 | |
| Barium | ppm | ■0 | 0 | |
| Boron | ppm | ■ <1 | 3 | |
| | | | | |



RIPA AND ASSOCIATES

10149 FISHER AVENUE
TAMPA, FL
US 33619
Contact: PM Services
PMServices@ripaconstruction.com
T:
F:

Diagnosis

We recommend you service the filters on this component. We recommend an early resample to monitor this condition. All component wear rates are normal. There is a moderate amount of silt (particulates < 14 microns in size) present in the oil. The AN level is acceptable for this fluid. The oil is still serviceable provided that the contaminant(s) can be reduced to acceptable levels.

Depot:RIPTAMUnique No:10655153Signed:Wes DavisReport Date:20 Sep 2023



CONSTRUCTION EQUIPMENT





GRAPHS

