

CONSTRUCTION EQUIPMENT VOLVO A30G 752905 - DIESEL ENGINE



Sample No: VCP414670

Oil Type: VOLVO ULTRA DIESEL ENGINE OIL 15W40 VDS-3

Job No:

SAMPLE	INFORMATION				
Sample Number		VCP414670	VCP424507	VCP397487	
Sample Date		11 Sep 2023	13 Jun 2023	22 Feb 2023	
Machine Hours		1802	1294	537	
Oil Hours		0	500	500	
Oil Changed		Changed	Changed	Changed	
Sample Status		NORMAL	ABNORMAL	ABNORMAL	
Sample Status		HORWAL	ADIVOITIVIAL	ADNONVAL	
VOLVO					
OIL CON	DITION				
Visc @ 100°C	cSt	12.5	12.7	1 0.6	
Base Number (BN	J) mg KOH/g	■9.6	7.3	5.7	
Oxidation (PA)	%	82	84	60	
TONTAN	IINATION				
_	<u>IIN</u> ATION				
Soot %	%	■ 0.2	1	□ 0.7	
Nitration (PA)	%	68	92	88	
Sulfation (PA)	%	60	67	59	
Glycol	%	NEG	NEG	NEG	
uel	%	<1.0	< 1.0	■ 0.5	
Silicon	ppm	6	9	△ 64	
Sodium	ppm	■3	2	< 1	
Potassium	ppm	■<1	1	5	
WEAR M	IFTAI S				
_		4	- 25	- 45	
ron	ppm	4	25	45	
Copper	ppm	1	<u> </u>	<u>▲</u> 382	
₋ead -·	ppm	■ <1	2	- <1	
Tin	ppm	■<1	2	4	
Aluminum	ppm	1	3	4	
Chromium	ppm	0	= <1	□ <1 □ <2 □ <2	
Molybdenum	ppm	■46	□ 50	■ 92	
Vickel	ppm	■ <1	1	2	
Titanium	ppm	0	<1	<1	
Silver	ppm	0	<1	<1	
Manganese	ppm		2	7	
/anadium	ppm	<1	<1	<1	
VOLVO					
ADDITIV	ES				
Calcium		m 1920	□ 1722	■ 2354	
Vagnesium	ppm	■ 1839 ■ 555	395	17	
viagnesium Zinc	ppm		1035	■ 1201	
Phosphorus	ppm	1225		■ 1201 ■ 1027	
•	ppm	1006	■834 ■0		
Barium	ppm	■ 0	0	2	



RIPA AND ASSOCIATES

10149 FISHER AVENUE
TAMPA, FL
US 33619
Contact: PM Services
PMServices@ripaconstruction.com
T:
F:

Diagnosis

Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the oil. The BN result indicates that there is suitable alkalinity remaining in the oil. The condition of the oil is suitable for further service.

Depot:RIPTAMUnique No:10675077Signed:Wes DavisReport Date:04 Oct 2023

ppm

Boron



CONSTRUCTION EQUIPMENT





