

CONSTRUCTION EQUIPMENT

SW0-067478 VOLVO EC380EL 310443 - SWING DRIVE



Sample No: VCP445783

Oil Type: NOT GIVEN

Job No: SWO-067478

SAMPLE	INFORMATION				
Sample Number		VCP445783	VCP395114	VCP387977	VCP366790
Sample Date		08 Nov 2023	14 Feb 2023	08 Nov 2022	19 Jul 2022
Machine Hours		10940	10082	9587	9113
Oil Hours		0	0	0	0
Oil Changed		Changed	Changed	Not Changd	Changed
Sample Status		SEVERE	SEVERE	SEVERE	SEVERE
OIL CON	DITION				
		·			
Visc @ 40°C	cSt	465	426	■361	■388
VOLVO					
CONTAM	IINATION				
Water	%	14.3	9.72	2.62	13.4
Silicon	ppm	■ 16	1 16	8	19
Sodium	ppm	■0	1 0	□0	2
Potassium	ppm	2	2	1 0	<u> </u>
VOLVO	IETAL C				
WEAR M	IF I ALS				
Iron	ppm	145	■199	■126	■388
Copper	ppm	18	1 8	1 1	■ 36
Lead	ppm	1	2	1	- <1
Tin	ppm	6	4	1	<1
Aluminum	ppm	■4	■3	2	4
Chromium	ppm	2	4	2	8
Molybdenum	ppm	<1	2	2	7
Nickel	ppm	■ <1	- <1	- <1	3
Titanium	ppm	<1	<1	0	<1
Silver	ppm	0	<1	<1	<1
Manganese	ppm	3	4	3	10
Vanadium	ppm	0	0	0	<1
VOLVO					
ADDITIV	ES				
Calcium	ppm	75	72	6 9	111
Magnesium	ppm	20	11	9	68
Zinc	ppm	73	68	□32	120
Phosphorus	ppm	918	900	■866	1103
Barium	ppm	0	0	0	0
Boron	ppm	107	134	■ 143	198
	P P				



WHITAKER CONTRACTING 692 CONVICT CAMP RD GUNTERSVILLE, AL US 35976 Contact: BROTHER WHITAKER BrotherWhitaker@whitaker-contracting.com T: (256)298-3905 F:

Diagnosis

We advise that you check for the source of water entry. The oil change at the time of sampling has been noted. We recommend an early resample to monitor this condition. All component wear rates are normal. There is a high concentration of water present in the oil. The oil is no longer serviceable due to the presence of contaminants.

Depot:WHIGUNUnique No:10749056Signed:Doug BogartReport Date:19 Nov 2023



CONSTRUCTION EQUIPMENT





