

CONSTRUCTION EQUIPMENT VOLVO ECR58F 11700 - COOLANT



Sample No: VCP319479

Job No:

| SAMPLE II | FORMATION | | | |
|--------------------|------------|-------------|---|------|
| Sample Number | - | VCP319479 | | |
| Sample Date | | 20 Nov 2023 | | |
| Machine Hours | | 1000 | | |
| Sample Status | | NORMAL | | |
| | | | | |
| COOLANT | CONDITION | | | |
| рН | Scale 0-14 | 7.86 | | |
| Reserve Alkalinity | Scale 0-20 | | | |
| Nitrites | ppm | NT 📃 | | |
| Percentage Glycol | % | 39.9 | | |
| Freezing Point | °C | -11 | | |
| | | | | |
| CONTAMIN | ATION | | _ | |
| Coolant Appearance | | normal | | |
| Coolant Color | | Yllow | | |



DH FUNK AND SONS LLC 3995 CONTINENTAL DRIVE COLUMBIA, PA US 17512 Contact: GARY SHEPHERD GSHEPHERD@DHFUNK.COM T: F:

Diagnosis

No corrective action is recommended at this time. The fluid is suitable for further service. There is no indication of any contamination in the coolant. Carboxylate test failed. The glycol level is acceptable. The pH level of this fluid is within the acceptable limits.

 Depot:
 DHFCOL

 Unique No:
 10756111

 Signed:
 Jonathan Hester

 Report Date:
 29 Nov 2023

CONSTRUCTION EQUIPMENT



GRAPHS

Iron/Tin/Silver

VOLVO

