

## CONSTRUCTION EQUIPMENT VOLVO L90H 625035 - REAR AXLE



Sample No: VCP444262

Job No:

Boron

	E INFORMATION	<u>.</u>	NCD204426	 
Sample Number		VCP444262	VCP381436	 
Sample Date		15 Feb 2024	30 Jan 2023	 
Machine Hours		3984	3010	 
Dil Hours		0	1000	 
Oil Changed		N/A	Not Changd	 
Sample Status		NORMAL	NORMAL	 
VOLVO				
💛 OIL CON	DITION			
Visc @ 40°C	cSt	48.0	47.6	 
VOLVO				
	MINATION			
Water	%	NEG	NEG	 
Silicon	ppm	22	21	 
Sodium	ppm	3	3	 
Potassium	ppm	■ <1	0	 
VOLVO				
WEAR N	METALS			
ron	ppm	77	62	 
Copper	ppm	<b>□</b> <i>11</i>	□ <1	 
_ead	ppm	2	□ <1	 
Fin	ppm	2	□ <1	 
Aluminum	ppm	1	1	 
Chromium	ppm	■ <1	2	 
Molybdenum	ppm	■<1	4	 
Nickel	ppm		0	 
Titanium	ppm	0	0	 
Silver	ppm	0	0	 
Manganese	ppm	3	5	 
Vanadium	ppm	0	0	 
	phill	U U	U	
VOLVO				 
ADDITI\	ES			
Calcium	ppm	3728	3837	 
Magnesium	ppm	<b>10</b>	15	 
Zinc	ppm	<b>1432</b>	1485	 
Phosphorus	ppm	<b>1220</b>	1175	 
Barium	ppm	0	0	 
P		- 494	- 100	

129



**RIPA AND ASSOCIATES** 

10149 FISHER AVENUE TAMPA, FL US 33619 Contact: PM Services PMServices@ripaconstruction.com T: F-

## Diagnosis

Resample at the next service interval to monitor.All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.

Depot:	RIPTAM		
Unique No:	10900831		
Signed:	Don Baldridge		
Report Date:	29 Feb 2024		

121


ppm

## **CONSTRUCTION EQUIPMENT**



GRAPHS

VOLVO



Report Id: RIPTAM [WUSCAR] 06102601 (Generated: 02/29/2024 20:37:14) Rev: 1

Contact/Location: PM Services ? - RIPTAM