

Sample No: VCP453909

Oil Type: VOLVO SUPER WET BRAKE TRANSAXLE OIL WB102

Job No: 687253 RENTALS

SAMPLI	E INFORMATION	١		
Sample Number		VCP453909	VCP418357	
Sample Date		08 Mar 2024	11 Jul 2023	
Machine Hours		1305	421	
Oil Hours		0	0	
Oil Changed		Not Changd	Not Changd	
Sample Status		ABNORMAL	NORMAL	
VOLVO	IDITION			
OIL CON	אטווועו			
Visc @ 40°C	cSt	44.6	44.3	
VOLVO				
CONTAN	MINATION			
Water	%	NEG	NEG	
Silicon		MEG ■ 16	14	
Sodium	ppm	■ 0	<u>4</u>	
Potassium	ppm	7	1 6	
Potassium	ppm	<i>I</i>	0	
VOLVO				
WEAR N	METALS			
Iron	ppm	9	□ 3	
Copper	ppm	221	■97	
Lead	ppm	1	1	
Tin	ppm	1	- <1	
Aluminum	ppm	2	 <1	
Chromium	ppm	■<1	- <1	
Molybdenum	ppm	1		
Nickel	ppm	1	0	
Titanium	ppm	<1	0	
Silver	ppm	<1	0	
Manganese	ppm	2	< 1	
Vanadium	ppm	<1	0	
ADDITIV	VES			
Calcium	ppm	□ 3761	□ 4297	
Magnesium	ppm	8	4	
Zinc	ppm	1428	□ 1639	
Phosphorus	ppm	1169	1369	
Barium	ppm	3	0	
Boron	ррт	131	158	
DOTOTI	ppili	131	<u> </u>	



ALTA EQUIPMENT/FLAGLER CONSTRUCTION EQUIPMENT LLC
8418 PALM RIVER ROAD
TAMPA, FL
US 33619
Contact: KENNY HANEY
khaney@flaglerce.com
T: (813)630-0077
F: (813)630-2233

Diagnosis

No corrective action is recommended at this time. Resample at the next service interval to monitor. The copper level is abnormal. All other component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.

Depot:VOLVO0093Unique No:10941415Signed:Don BaldridgeReport Date:27 Mar 2024



CONSTRUCTION EQUIPMENT





GRAPHS

