VOLVO

CONSTRUCTION EQUIPMENT SW0-071394 VOLVO A60H 350187 - GEARBOX



Sample No:VCP452739Oil Type:{unknown}Job No:SWO-071394

	E INFORMATION			
		VCP452739	VCP428920	
Sample Number				
Sample Date		29 Apr 2024	06 Sep 2023	
Machine Hours		3015	2021	
Oil Hours		0	0	
Oil Changed		Not Changd	Not Changd	
Sample Status		ABNORMAL	NORMAL	
OIL CON	IDITION			
Visc @ 40°C	cSt	45.4	49.5	
VOLVO				
🤍 CONTAI	MINATION			
Water	%	NEG	NEG	
Silicon	ppm	28	19	
Sodium	ppm	9	3	
Potassium	ppm	3	4	
VOLVO	AFTALC			
WEAR I	METALS			
Iron	ppm	73	84	
Copper	ppm	A 384	 <1	
Lead	ppm	 <1	<1	
Tin	ppm		0	
Aluminum	ppm	2	0	
Chromium	ppm		□ <1	
Molybdenum	ppm	2	<1	
Nickel	ppm	4	<1	
Titanium	ppm	<1	0	
Silver	ppm	0	0	
Manganese	ppm	4	3	
Vanadium	ppm	<1	0	
	221	•••	0	
VOLVO				

ADDITIVES 4223 Calcium 371 ppm Magnesium 26 4 ppm 1519 164 Zinc ppm Phosphorus ppm 1396 2421 Barium ppm 0 0 185 283 Boron ppm

SAIIA CONSTRUCTION LLC

4400 LEWISBURG RD BIRMINGHAM, AL US 35207 Contact: STEPHANI BRITTON sbritton@saiia.com;doug.bogart@wearcheck.com T: (205)943-2268 F: (205)943-2269

Diagnosis

No corrective action is recommended at this time. Resample at the next service interval to monitor.Bearing and/or bushing wear is indicated. All other component wear rates are normal. Moderate concentration of visible dirt/debris present in the oil. The condition of the oil is acceptable for the time in service.


Depot:SAIBIRUnique No:11009473Signed:Don BaldridgeReport Date:07 May 2024Contact/Location: STEPHANI BRITTON - SAIBIR

CONSTRUCTION EQUIPMENT



GRAPHS

VOLVO



Report Id: SAIBIR [WUSCAR] 06168754 (Generated: 05/07/2024 16:25:44) Rev: 1

Contact/Location: STEPHANI BRITTON - SAIBIR