

CONSTRUCTION EQUIPMENT

TADANO GR800XL-4 RA 1639 - DIESEL ENGINE



Sample No: VCP439919

Oil Type: VOLVO VDS-4.5 Premium Motor Oil 15W40

Job No: X48968

VCP439919 07 May 2024 2565 2565 Changed MARGINAL 111.9 OH/g 9.1 66	 		
VCP439919 07 May 2024 2565 2565 Changed MARGINAL			
07 May 2024 2565 2565 Changed MARGINAL			
2565 2565 Changed MARGINAL			
2565 Changed MARGINAL 11.9 OH/g 9.1			
Changed MARGINAL 11.9 DH/g 9.1			
MARGINAL □ 11.9 □ Hyg □ 9.1			
■11.9 OH/g ■9.1			
OH/g ■9.1			
66			
NEC		<u> </u>	
_			
_			
_			
■4			
■15			
_			
_			
_			
_			
<1			
	NEG 0.3 61 55 NEG 2.7 8 00 4 15 4	□0.3 61 55 NEG NEG 8 0 15 4 < < < < < < < < < < < < < < < < < < < < < < < < < < < < < < < < < < < < < < < < < < < < < < < < < < < < < < < < < < < < < < < < < < < < < < < < < < < < < < < < < < < < < < < < < < < < < < < < < < < < < < < < < < < < <	□0.3 61 55 NEG NEG 8 0 15 15 14 15



SCOTT EQUIPMENT COMPANY LLC - Lake Charles
PO BOX 16955
LAKE CHARLES, LA
US 70616
Contact: SAMANTHA SOILEAU
ssoileau@scottcompanies.com
T: (337)433-9811
F: (318)433-6623

Diagnosis

The oil change at the time of sampling has been noted. Resample at the next service interval to monitor. No other corrective action is recommended at this time.Metal levels are typical for a components first oil change. Light fuel dilution occurring. No other contaminants were detected in the oil. The BN result indicates that there is suitable alkalinity remaining in the oil. The condition of the oil is suitable for further service.

Depot:VOLVO6244Unique No:11022897Signed:Wes DavisReport Date:15 May 2024

ppm

ppm

ppm

ppm

ppm

ppm

1122

■830

■ 1150
■ 1052

3

13

Calcium

Zinc

Barium

Boron

Magnesium

Phosphorus



CONSTRUCTION EQUIPMENT





