

CONSTRUCTION EQUIPMENT PRINCE VOLVO L90H 626620 - FRONT AXLE



Sample No: VCP440241
Oil Type: VOLVO WB 102

Job No: PRINCE

VOLVO	E INFORMATION				
	INFURMATION				
Sample Number		VCP440241	VCP417589		
Sample Date		07 Jun 2024	30 Jun 2023		
Machine Hours		3112	1057		
Oil Hours		0	1057		
Oil Changed		Not Changd	Changed		
Sample Status		ABNORMAL	NORMAL		
VOLVO					
OIL CON	IDITION				
Visc @ 40°C	cSt	43.4	41.5		
VOLVO					
CONTAN	MINATION				
_		△ 0.447	NEC		
Water	%		NEG		
Silicon	ppm	■13	2 2		
Sodium	ppm	■0	4		
Potassium	ppm	■ 2	■0		
VOLVO					
WEAR N	METALS				
Iron	ppm	□ 26	1 74		
Copper	ppm	- <1	0		
Lead	ppm	1 <1	0		
Tin	ppm	<1	0		
Aluminum	ppm	2	1 2		
Chromium	ppm	■ <1	1 4		
Molybdenum	ppm	1	23		
Nickel	ppm	■0	0		
Titanium	ppm	<1	<1		
Silver	ppm	0	0		
Manganese	ppm	■ 1	1 1		
Vanadium	ppm	0	0		
variaululli	ppill	U	U	-2-	
VOLVO					
ADDITIV	VES				
Calcium	ppm	■3913	4179		
Magnesium	ppm	■ 15	1 6		
Zinc	ppm	1576	□ 1729		
Phosphorus	ppm	■1173	1390		
Barium	ppm	■0	0		
Boron	ppm	149	150		
_ 3. 3	PP.11				



ALTA EQUIPMENT/FLAGLER CONSTRUCTION EQUIPMENT LLC
8418 PALM RIVER ROAD
TAMPA, FL
US 33619
Contact: KENNY HANEY
khaney@flaglerce.com
T: (813)630-0077
F: (813)630-2233

Diagnosis

We advise that you check for the source of water entry. Resample at the next service interval to monitor. All component wear rates are normal. There is a moderate concentration of water present in the oil. The condition of the oil is acceptable for the time in service.

Depot:VOLVO0093Unique No:11075556Signed:Don BaldridgeReport Date:14 Jun 2024

Contact/Location: KENNY HANEY - VOLVO0093



CONSTRUCTION EQUIPMENT





