

CONSTRUCTION EQUIPMENT VOLVO ECR 145 3 16780 - REAR LEFT FINAL DRIVE



Sample No: VCP439886

Oil Type: GEAR OIL SAE 85W140

Job No:

SAMPLE	INFORMATION			
Sample Number		VCP439886	 	
Sample Date		11 Jun 2024	 	
Machine Hours		516	 	
Oil Hours		0	 	
Oil Changed		Changed	 	
Sample Status		ABNORMAL	 	
		7.5.1.01		
VOLVO	DITION			
OIL CON	ULLION			
Visc @ 40°C	cSt	137	 	
CUNTAN	IINATION			
_		·	 <u> </u>	
Water	%	NEG	 	
Silicon	ppm	16	 	
Sodium	ppm	4	 	
Potassium	ppm	■1	 	
VOLVO				
WEAR M	IETALS			
Iron	ppm	□ 317	 	
Copper	ppm	■<1	 	
Lead	ppm	1 <1	 	
Tin	ppm	<u>△</u> 23	 	
Aluminum	ppm	1	 	
Chromium	ppm	6	 	
Molybdenum	ppm	1 <1	 	
Nickel	ppm	- <1	 	
Titanium	ppm	<1	 	
Silver	ppm	0	 	
Manganese	ppm	■4	 	
Vanadium	ppm	0	 	
	le le			
VOLVO	re			
ADDITIV	F7			
Calcium	ppm	■ 6	 	
Magnesium	ppm	■1	 	
Zinc	ppm	■31	 	
Phosphorus	ppm	■252	 	
Barium	ppm	-<1	 	
Boron	ppm	■ 0	 	



RIPA AND ASSOCIATES 10149 FISHER AVENUE TAMPA, FL US 33619 Contact: PM Services PMServices@ripaconstruction.com

F:

Diagnosis

The oil change at the time of sampling has been noted. No corrective action is recommended at this time. Resample at the next service interval to monitor. The tin level is abnormal. All other component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.

Depot:RIPTAMUnique No:11083351Signed:Sean FeltonReport Date:18 Jun 2024

Contact/Location: PM Services ? - RIPTAM



CONSTRUCTION EQUIPMENT





GRAPHS

