



CONSTRUCTION EQUIPMENT

SWO-072798 APAC AL WEILER 2850A 1533 - FRONT RIGHT FINAL DRIVE



Sample No: VCP443981
Oil Type: {unknown}
Job No: SWO-072798 APAC AL



SAMPLE INFORMATION

Sample Number	VCP443981	---	---	---
Sample Date	11 Jun 2024	---	---	---
Machine Hours	4072	---	---	---
Oil Hours	0	---	---	---
Oil Changed	Changed	---	---	---
Sample Status	ABNORMAL	---	---	---

COWIN EQUIPMENT COMPANY

2238 PINSON VALLEY PARKWAY
BIRMINGHAM, AL
US 35217
Contact: BRANTLY CLAY
bclay@cowin.com
T:
F: (205)856-2106



OIL CONDITION

Visc @ 40°C	cSt	█ 200	---	---	---
-------------	-----	-------	-----	-----	-----



CONTAMINATION

Water	%	NEG	---	---	---
Silicon	ppm	█ 10	---	---	---
Sodium	ppm	█ 2	---	---	---
Potassium	ppm	█ 3	---	---	---



WEAR METALS

Iron	ppm	█ 297	---	---	---
Copper	ppm	▲ 73	---	---	---
Lead	ppm	█ <1	---	---	---
Tin	ppm	█ 2	---	---	---
Aluminum	ppm	█ 2	---	---	---
Chromium	ppm	█ 4	---	---	---
Molybdenum	ppm	1	---	---	---
Nickel	ppm	█ <1	---	---	---
Titanium	ppm	<1	---	---	---
Silver	ppm	<1	---	---	---
Manganese	ppm	1	---	---	---
Vanadium	ppm	<1	---	---	---



ADDITIVES

Calcium	ppm	8	---	---	---
Magnesium	ppm	2	---	---	---
Zinc	ppm	45	---	---	---
Phosphorus	ppm	264	---	---	---
Barium	ppm	5	---	---	---
Boron	ppm	8	---	---	---

Diagnosis

The oil change at the time of sampling has been noted. No corrective action is recommended at this time. Resample at the next service interval to monitor. The copper level is abnormal. All other component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.

Depot: VOLVO8528
Unique No: 11085017
Signed: Don Baldrige
Report Date: 19 Jun 2024



CONSTRUCTION EQUIPMENT



GRAPHS

