

## **CONSTRUCTION EQUIPMENT** VOLVO A30G 752302 - WET DISC BRAKE



 Sample No:
 VCP06212154

 Oil Type:
 VOLVO WB 102

#### Job No:

	E INFORMATION	l		
Sample Number	-	VCP06212154	VCP351618	 
Sample Date		12 Jun 2024	17 Feb 2022	 
Machine Hours		5450	983	 
Oil Hours		0	1500	 
Oil Changed		Not Changd	Not Changd	 
Sample Status		ABNORMAL	NORMAL	 
OIL CON	DITION			
Visc @ 40°C	cSt	43.8	103	 
CONTAN	MINATION			
Water	%	NEG	NEG	 
Silicon	ppm	<b>12</b>	10	 
Sodium	ppm	5	0	 
Potassium	ppm	3	4	 
		_	_	
WEAR N	METALS			
Iron	ppm	<b>1</b> 5	16	 
Copper	ppm	<b>480</b>	6	 
Lead	ppm		<1	 
Tin	ppm	<b></b> <1	1	 
Aluminum	ppm	2	7	 
Chromium	ppm	<b>  </b> <1	<b></b> <1	 
Molybdenum	ppm	<b>1</b>	81	 
Nickel	ppm	2	0	 
Titanium	ppm	<1	<1	 
Silver	ppm	<1	0	 
Manganese	ppm	2	<b></b> < 1	 
Vanadium	ppm	<1	0	 

Applitae2							
Calcium	ppm	3499	1660				
Magnesium	ppm	<b>12</b>	472				
Zinc	ppm	<b>1202</b>	1341				
Phosphorus	ppm	1188	1118				
Barium	ppm	2	0				
Boron	ppm	<b>111</b>	425				



#### **RIPA AND ASSOCIATES**

10149 FISHER AVENUE TAMPA, FL US 33619 Contact: PM Services PMServices@ripaconstruction.com T: F:

### Diagnosis

The filter change at the time of sampling has been noted. We recommend an early resample to monitor this condition.The copper level is abnormal. Moderate concentration of visible dirt/debris present in the oil. The condition of the oil is acceptable for the time in service.


Depot:RIPTAMUnique No:11085018Signed:Don BaldridgeReport Date:19 Jun 2024Contact/Location: PM Services ? - RIPTAM

# **CONSTRUCTION EQUIPMENT**



GRAPHS

VOLVO



Report Id: RIPTAM [WUSCAR] 06212154 (Generated: 06/21/2024 14:24:08) Rev: 1

Contact/Location: PM Services ? - RIPTAM