



# CONSTRUCTION EQUIPMENT

1036529 BALCONES VOLVO L120H 633369 - TRANSMISSION (AUTO)



**Sample No:** VCP06220233  
**Oil Type:** VOLVO AT 102  
**Job No:** 1036529 BALCONES



## SAMPLE INFORMATION

Sample Number	VCP06220233	---	---	---
Sample Date	18 Jun 2024	---	---	---
Machine Hours	3669	---	---	---
Oil Hours	0	---	---	---
Oil Changed	N/A	---	---	---
Sample Status	NORMAL	---	---	---

**ARNOLD MACHINERY COMPANY**  
4323 EAST WINSLOW AVENUE  
PHOENIX, AZ  
US 85040  
Contact: RANDY PRZEKURAT  
randyp@arnoldmachinery.com  
T:  
F: (602)414-1904



## OIL CONDITION

Visc @ 40°C	cSt	█ 27.7	---	---	---
-------------	-----	--------	-----	-----	-----



## CONTAMINATION

Water	%	NEG	---	---	---
Silicon	ppm	█ 9	---	---	---
Sodium	ppm	█ 5	---	---	---
Potassium	ppm	█ <1	---	---	---

## Diagnosis

Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the fluid. The condition of the fluid is acceptable for the time in service.



## WEAR METALS

Iron	ppm	█ 41	---	---	---
Copper	ppm	█ 25	---	---	---
Lead	ppm	█ 0	---	---	---
Tin	ppm	█ 0	---	---	---
Aluminum	ppm	█ 7	---	---	---
Chromium	ppm	█ 0	---	---	---
Molybdenum	ppm	█ 0	---	---	---
Nickel	ppm	█ 0	---	---	---
Titanium	ppm	0	---	---	---
Silver	ppm	█ 0	---	---	---
Manganese	ppm	█ 5	---	---	---
Vanadium	ppm	0	---	---	---



## ADDITIVES

Calcium	ppm	█ 81	---	---	---
Magnesium	ppm	█ <1	---	---	---
Zinc	ppm	7	---	---	---
Phosphorus	ppm	█ 178	---	---	---
Barium	ppm	█ 2	---	---	---
Boron	ppm	█ 64	---	---	---

**Depot:** VOLVO6174  
**Unique No:** 11098430  
**Signed:** Wes Davis  
**Report Date:** 26 Jun 2024




# CONSTRUCTION EQUIPMENT




## GRAPHS


### Iron (ppm)




### Lead (ppm)



### Aluminum (ppm)




### Chromium (ppm)




### Copper (ppm)



### Silicon (ppm)



### Viscosity @ 40°C



### Additives

