



PAULA SPINA 6186 TWIN DISC 5061SC 5JE607 - INBOARD GEARBOX

Sample No: VPA045824
Oil Type: NOT GIVEN

SAMPLE INFORM	ATION			
Sample Number		VPA045824	 	
Sample Date		13 Jul 2023	 	
Machine Hours		4506	 	
Oil Hours		0	 	
Oil Changed		Not Changd	 	
Sample Status		ATTENTION	 	
		711121111011		
OIL CONDITION				
Visc @ 40°C	cSt	113.0	 	
CONTAMINATION				
Silicon	ppm	■ 4	 	
Sodium	ppm	1	 	
Potassium	ppm	<u> </u>	 	
WEAR METALS				
PQ		2 1	 	
Iron	ppm	<u></u> 30	 	
Copper	ppm	<u> </u>	 	
Lead	ppm	A 225	 	
Tin	ppm	4	 	
Aluminum	ppm	2	 	
Chromium	ppm	□ <1	 	
Molybdenum	ppm	15	 	
Nickel	ppm	□ <1	 	
Titanium	ppm	<1	 	
Silver	ppm	2	 	
Manganese	ppm	<1	 	
Vanadium	ppm	<1	 	
ZAVITIDDA				
Calcium	ppm	2779	 	
Magnesium	ppm	280	 	
Zinc	ppm	1484	 	
Phosphorus	ppm	1344	 	
Barium	ppm	0	 	
Boron	ppm	118	 	

Northwest Diesel Power

1325 ROEDER AVE SUITE 103 BELLINGHAM, WA US 98225

Contact: BRANDON ROBERTSON parts@nwdieselpower.com

T: F:

Diagnosis

No corrective action is recommended at this time. Resample at the next service interval to monitor. Clutch wear is indicated. Wear rates are normal for OEM. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.

Depot:VP759009Unique No:10560495Signed:Doug BogartReport Date:14 Jul 2023

OIL ANALYSIS REPORT



