

PROBLEM SUMMARY

Sample Rating Trend

12006 Aug2007 Nov2008 May2010 May2011 May2011 May2012 Madate a dota




COMMON BEARING SUMP FOR MULTIPLE BEARINGS TOP G BRG

Component Bearing

MOBIL DTE OIL HVY MEDIUM (90 LTR)

COMPONENT CONDITION SUMMARY



RECOMMENDATION

We recommend you service the filters on this component. We recommend an early resample to monitor this condition. (Customer Sample Comment: Sample taken after 1hr 30min at 2150 kw after new bearing installed following thrust collar repair.)

PROBLEMATIC TEST I	RESULTS				
Sample Status			ABNORMAL	ATTENTION	ABNORMAL
Particles >4µm	ASTM D7647	>10000	A 34481	<u>▲</u> 15931	<u>^</u> 72174
Particles >6µm	ASTM D7647	>2500	3038	1604	<u></u> 10260
Oil Cleanliness	ISO 4406 (c)	>20/18/14	22/19/12	<u>\(21/18/11</u>	A 23/21/15

Customer Id: NEWSTJ Sample No.: WC0455666 Lab Number: 02554156 Test Package: IND 2



To manage this report scan the QR code

To discuss the diagnosis or test data: Kevin Marson +1 (289)291-4644 x4644 Kevin.Marson@wearcheck.com

To change component or sample information: Gloria Gonzalez +1 (289)291-4643 x4643 gloria.gonzalez@wearcheck.com

Action Status Date Done By Description

Resample	MISSED	Jun 12 2023	?	We recommend an early resample to monitor this condition.

We recommend you service the filters on this component.

HISTORICAL DIAGNOSIS

21 Nov 2022 Diag: Kevin Marson

MISSED

Jun 12 2023



Change Filter

We recommend you service the filters on this component. Resample at the next service interval to monitor. All component wear rates are normal. There is a light amount of silt (particulates < 14 microns in size) present in the oil. The AN level is acceptable for this fluid. The condition of the oil is suitable for further service.



03 Mar 2022 Diag: Kevin Marson





We recommend you service the filters on this component. We recommend an early resample to monitor this condition.All component wear rates are normal. Particles >4µm are abnormally high. Particles >6µm are abnormally high. Particles >14µm are notably high. Particles >21µm are notably high. The AN level is acceptable for this fluid. The condition of the oil is suitable for further service.



02 May 2019 Diag: Wes Davis





We advise that you perform a filter service, and use off-line filtration to improve the cleanliness of the system fluid. We recommend an early resample to monitor this condition. All component wear rates are normal. Particles >14 μ m are abnormally high. Particles >21 μ m are abnormally high. Particles >6 μ m are abnormally high. The AN level is acceptable for this fluid. The condition of the oil is suitable for further service.





OIL ANALYSIS REPORT

SAMPLE INFORMATION method

ISO

history1

COMMON BEARING SUMP FOR MULTIPLE BEARINGS **TOP G BRG**

Component

Bearing

MOBIL DTE OIL HVY MEDIUM (90 LTR)

DIAGNOSIS

Recommendation

We recommend you service the filters on this component. We recommend an early resample to monitor this condition. (Customer Sample Comment: Sample taken after 1hr 30min at 2150 kw after new bearing installed following thrust collar repair.)

Wear


All component wear rates are normal.

Contamination

There is a moderate amount of silt (particulates < 14 microns in size) present in the oil.

Fluid Condition

The AN level is acceptable for this fluid. The oil is still serviceable provided that the contaminant(s) can be reduced to acceptable levels.




current

limit/base

Sample Number		Client Info		WC0455666	WC0455606	WC0445328
Sample Date		Client Info		21 Feb 2023	21 Nov 2022	03 Mar 2022
Machine Age	hrs	Client Info		0	0	0
Oil Age	hrs	Client Info		0	0	0
Oil Changed		Client Info		N/A	N/A	N/A
Sample Status				ABNORMAL	ATTENTION	ABNORMAL
CONTAMINATION	N	method	limit/base	current	history1	history2
Water		WC Method	>2	NEG	NEG	NEG
WEAR METALS		method	limit/base	current	history1	history2
PQ		ASTM D8184*		0	0	0
Iron	ppm	ASTM D5185(m)	>63	<1	<1	<1
Chromium	ppm	ASTM D5185(m)	>20	0	0	0
Nickel	ppm	ASTM D5185(m)	>20	<1	0	<1
Titanium	ppm	ASTM D5185(m)		<1	0	0
Silver	ppm	ASTM D5185(m)		0	0	0
Aluminum	ppm	ASTM D5185(m)	>2	0	0	0
Lead	ppm	ASTM D5185(m)	>161	3	9	4
Copper	ppm	ASTM D5185(m)	>13	<1	<1	<1
Tin	ppm	ASTM D5185(m)	>27	<1	0	<1
Antimony	ppm	ASTM D5185(m)		<1	<1	<1
Vanadium	ppm	ASTM D5185(m)		0	0	0
Beryllium	ppm	ASTM D5185(m)		0	0	0
Cadmium	ppm	ASTM D5185(m)		<1	<1	0
ADDITIVES		method	limit/base	current	history1	history2
Boron	ppm	ASTM D5185(m)		<1	<1	<1
Barium	ppm	ASTM D5185(m)		0	0	0
Molybdenum	ppm	ASTM D5185(m)		0	0	0
Manganese	ppm	ASTM D5185(m)		0	0	0
Magnesium	ppm	ASTM D5185(m)		0	0	0
Calcium	ppm	ASTM D5185(m)		0	0	<1
Phosphorus	ppm	ASTM D5185(m)		162	132	134
Zinc	ppm	ASTM D5185(m)		79	67	77
Sulfur	ppm	ASTM D5185(m)		812	464	451
Lithium	ppm	ASTM D5185(m)		<1	<1	<1
CONTAMINANTS	}	method	limit/base	current	history1	history2
Silicon	ppm	ASTM D5185(m)	>12	<1	<1	1
Sodium	ppm	ASTM D5185(m)		0	<1	0
Potassium	ppm	ASTM D5185(m)	>20	0	<1	<1



OIL ANALYSIS REPORT





CALA ISO 17025:2017 Accredited

Laboratory

Laboratory Sample No. Lab Number **Unique Number**

: WearCheck - C8-1175 Appleby Line, Burlington, ON L7L 5H9 : WC0455666 . 02554156

Received : 5567171

: 28 Apr 2023 Diagnosed : 02 May 2023 Diagnostician : Kevin Marson Test Package : IND 2 (Additional Tests: PRTCOUNT, TAN Man)

To discuss this sample report, contact Customer Service at 1-800-268-2131. Test denoted (*) outside scope of accreditation, (m) method modified, (e) tested at external lab. Validity of results and interpretation are based on the sample and information as supplied.

NEWFOUNDLAND POWER INC. 50 DUFFY PLACE, PO BOX 8910

ST. JOHNS, NL CA A1B 3P6

Contact: Paul Martin pmartin@newfoundlandpower.com

F: (709)737-2926

Submitted By: Brian Priddle

T: