


PROBLEM SUMMARY

Area (C-FIYQ) Machine Id [C-FIYQ] CESSNA 414 237118-R

Left Piston Aircraft Engine

AVIATION ENGINE OIL SAE 15W50 (12 GAL)

COMPONENT CONDITION SUMMARY



RECOMMENDATION

We advise that you check for a possible too-lean mixture, or an over-advanced ignition timing. The oil change at the time of sampling has been noted. We recommend an early resample to monitor this condition. The fluid was not specified, however, a fluid match indicates that this fluid is (GENERIC) AVIATION ENGINE OIL SAE 15W50. Please confirm.

PROBLEMATIC TEST RESULTS

Sample Status				ABNORMAL	
Aluminum	ppm	ASTM D5185(m)	>25	<u> </u>	


Customer Id: ITPLON Sample No.: WC0844064 Lab Number: 02577153 Test Package: AVI 1



To manage this report scan the QR code

To discuss the diagnosis or test data: Kevin Marson +1 (289)291-4644 x4644 Kevin.Marson@wearcheck.com

To change component or sample information: Gloria Gonzalez +1 (289)291-4643 x4643 gloria.gonzalez@wearcheck.com



RECOMMENDED ACTIONS						
Action	Status	Date	Done By	Description		
Resample			?	We recommend an early resample to monitor this condition.		
Alert			?	The fluid was not specified, however, a fluid match indicates that this fluid is (GENERIC) AVIATION ENGINE OIL SAE 15W50. Please confirm.		
Information Required			?	The fluid was not specified, however, a fluid match indicates that this fluid is (GENERIC) AVIATION ENGINE OIL SAE 15W50. Please confirm.		
Check Timing			?	We advise that you check for a possible too-lean mixture, or an over- advanced ignition timing.		

HISTORICAL DIAGNOSIS



OIL ANALYSIS REPOR

SAMPLE INFORMA

Sample Number

Sample Date

Oil Changed

Sample Status

CONTAMINATION

WEAR METALS

ppm

ppm

ppm

ppm

ppm

ppm

ppm

TSN

TSO

Fuel

Glycol

PQ

Iron

Nickel

Silver

Lead

Tin

Copper

Antimony

Vanadium

Beryllium

Cadmium

Chromium

Titanium

Aluminum

Oil Age

(C-FIYQ) [C-FIYQ] CESSNA 414 237118-R

Left Piston Aircraft Engine Flui

AVIATION ENGINE OIL SAE 15W50 (12 GAL)

DIAGNOSIS

Recommendation

We advise that you check for a possible too-lean mixture, or an over-advanced ignition timing. The oil change at the time of sampling has been noted. We recommend an early resample to monitor this condition. The fluid was not specified, however, a fluid match indicates that this fluid is (GENERIC) AVIATION ENGINE OIL SAE 15W50. Please confirm.

A Wear

Aluminum ppm levels are abnormal. High Aluminum (Al) level indicates abnormal bearing wear.

Contamination

There is no indication of any contamination in the oil.

Fluid Condition

The oil is no longer serviceable as a result of the abnormal and/or severe wear.

RT	Samp	le Rating Tre	nd		WEAR
IATION	method	limit/base	current	history1	history2
	Client Info		WC0844064		
	Client Info		10 Aug 2023		
hrs	Client Info		0		
hrs	Client Info		269		
hrs	Client Info		0		
	Client Info		Changed		
			ABNORMAL		
J	method	limit/base	current	history1	history2
	WC Method	>4.0	<1.0		
	WC Method		NEG		
	method	limit/base	current	history1	history2
	ASTM D8184*		7		
ppm	ASTM D5185(m)	>90	114		
ppm	ASTM D5185(m)	>20	32		
ppm	ASTM D5185(m)	>15	14		
ppm	ASTM D5185(m)		<1		
ppm	ASTM D5185(m)	>5	0		
ppm	ASTM D5185(m)	>25	<u> </u>		

ADDITIVES		method	limit/base	current	history1	history2
Boron	ppm	ASTM D5185(m)	5	<1		
Barium	ppm	ASTM D5185(m)	5	0		
Molybdenum	ppm	ASTM D5185(m)	12	9		
Manganese	ppm	ASTM D5185(m)		0		
Magnesium	ppm	ASTM D5185(m)	5	2		
Calcium	ppm	ASTM D5185(m)	5	2		
Phosphorus	ppm	ASTM D5185(m)	1000	1201		
Zinc	ppm	ASTM D5185(m)	12	8		
Sulfur	ppm	ASTM D5185(m)	3500	1756		
Lithium	ppm	ASTM D5185(m)		<1		
CONTAMINANTS		method	limit/base	current	history1	history2
Silicon	ppm	ASTM D5185(m)	>15	9		
Sodium	ppm	ASTM D5185(m)		<1		
Potassium	ppm	ASTM D5185(m)	>20	<1		

>20000

>25

ASTM D5185(m)

ASTM D5185(m)

ASTM D5185(m)

ASTM D5185(m)

ASTM D5185(m)

ASTM D5185(m)

ASTM D5185(m) >30

5511

14

2 0


0

0

2



OIL ANALYSIS REPORT



Contact/Location: Shannon Hickey - ITPLON