

PROBLEM SUMMARY

Sample Rating Trend




Machine Id

Bow Thruster Wartsila FT 175 BT (S/N PAAF589818)


Bow Thruster

PETRO CANADA ENDURATEX EP 100 (500 LTR)





COMPONENT CONDITION SUMMARY



RECOMMENDATION

We recommend you service the filters on this component. Resample at the next service interval to monitor.

PROBLEMATIC T	EST RESULTS				
Sample Status			ATTENTION	ABNORMAL	SEVERE
Particles >4µm	ASTM D7647	>5000	5949	<u>4</u> 24589	63496
Oil Cleanliness	ISO 4406 (c)	>19/17/14	20/16/12	<u>22/19/14</u>	23/19/13

Customer Id: MARTHABLAC Sample No.: WC0783691 Lab Number: 02585847 Test Package: MAR 2

To manage this report scan the QR code

To discuss the diagnosis or test data: Wes Davis +1 905-569-8600 x223 wesd@wearcheck.ca

To change component or sample information: Gloria Gonzalez +1 (289)291-4643 x4643 gloria.gonzalez@wearcheck.com

RECOMMENDED ACTIONS

Action	Status	Date	Done By	Description
Change Filter			?	We recommend you service the filters on this component.

HISTORICAL DIAGNOSIS

07 Jul 2021 Diag: Wes Davis





We recommend you service the filters on this component. We recommend an early resample to monitor this condition.All component wear rates are normal. Particles >4µm are abnormally high. Particles >6µm are abnormally high. The AN level is acceptable for this fluid. The condition of the oil is suitable for further service.



23 Jun 2020 Diag: Kevin Marson





Check seals and/or filters for points of contaminant entry. The air breather requires service. If unrated, we recommend that you replace with a suitable micron rated and/or desiccant air breather. If rated, we recommend that you service/replace the breather. We recommend you service the filters on this component. Resample in 30-45 days to monitor this situation.All component wear rates are normal. Particles >4µm are severely high. Particles >6µm are abnormally high. The AN level is acceptable for this fluid. The condition of the oil is suitable for further service.



07 Mar 2020 Diag: Kevin Marson

150



Check seals and/or filters for points of contaminant entry. The air breather requires service. If unrated, we recommend that you replace with a suitable micron rated and/or desiccant air breather. If rated, we recommend that you service/replace the breather. We recommend you service the filters on this component. Resample in 30-45 days to monitor this situation. All component wear rates are normal. Particles >4 μ m are severely high. Particles >6 μ m are notably high. The AN level is acceptable for this fluid. The condition of the oil is suitable for further service.





OIL ANALYSIS REPORT

Sample Rating Trend



Bow Thruster Wartsila FT 175 BT (S/N PAAF589818)

Bow Thruster

PETRO CANADA ENDURATEX EP 100 (500

DIAGNOSIS

Recommendation

We recommend you service the filters on this component. Resample at the next service interval to monitor.

All component wear rates are normal.

Contamination

There is a light amount of silt (particulates < 14 microns in size) present in the oil.


Fluid Condition

The AN level is acceptable for this fluid. The condition of the oil is suitable for further service.

LTR)		Sep 2017	Dec2018 Jun2019	Mar2020 Jun2020 Jul2021	Sep2023	
SAMPLE INFORM	MATION	method	limit/base	current	history1	history2
Sample Number		Client Info		WC0783691	WC	WC
Sample Date		Client Info		20 Sep 2023	07 Jul 2021	23 Jun 2020
Machine Age	hrs	Client Info		0	0	0
Oil Age	hrs	Client Info		0	0	0
Oil Changed		Client Info		N/A	N/A	N/A
Sample Status				ATTENTION	ABNORMAL	SEVERE
WEAR METALS		method	limit/base	current	history1	history2
Iron	ppm	ASTM D5185(m)	>90	8	1	2
Chromium	ppm	ASTM D5185(m)	>10	0	0	0
Nickel	ppm	ASTM D5185(m)	>10	<1	<1	<1
Titanium	ppm	ASTM D5185(m)		0	0	0
Silver	ppm	ASTM D5185(m)		0	0	0
Aluminum	ppm	ASTM D5185(m)	>10	0	0	<1
Lead	ppm	ASTM D5185(m)	>20	0	0	0
Copper	ppm	ASTM D5185(m)	>20	<1	<1	<1
Tin	ppm	ASTM D5185(m)	>15	0	0	0
Antimony	ppm	ASTM D5185(m)		0	0	<1
Vanadium	ppm	ASTM D5185(m)		0	0	0
Beryllium	ppm	ASTM D5185(m)		0	0	0
Cadmium	ppm	ASTM D5185(m)		0	0	0
ADDITIVES		method	limit/base	current	history1	history2
Boron	ppm	ASTM D5185(m)	50	56	63	64
Barium	ppm	ASTM D5185(m)	0	<1	0	<1
Molybdenum	ppm	ASTM D5185(m)	0	0	<1	0
Manganese	ppm	ASTM D5185(m)	0	0	0	0
Magnesium	ppm	ASTM D5185(m)	0	<1	<1	<1
Calcium	ppm	ASTM D5185(m)	0	3	2	1
Phosphorus	ppm	ASTM D5185(m)	270	244	268	255
Zinc	ppm	ASTM D5185(m)	0	9	5	5
Sulfur	ppm	ASTM D5185(m)	4500	3994	4488	4648
Lithium	ppm	ASTM D5185(m)		<1	<1	<1
CONTAMINANTS	3	method	limit/base	current	history1	history2
Silicon	ppm	ASTM D5185(m)	>7	5	5	8
Sodium	ppm	ASTM D5185(m)		2	<1	<1
Potassium	ppm	ASTM D5185(m)	>20	0	<1	<1
FLUID CLEANLIN	IESS	method	limit/base	current	history1	history2
Particles >4µm		ASTM D7647	>5000	5949	24589	63496
Particles >6µm		ASTM D7647	>1300	342	2946	4284
Particles >14µm		ASTM D7647	>160	26	84	52
Particles >21µm		ASTM D7647	>40	9	18	13
Particles >38µm		ASTM D7647	>10	1	1	0
Particles >71µm		ASTM D7647	>3	0	0	0
Oil Cleanliness		ISO 4406 (c)	>19/17/14	<u>^</u> 20/16/12	<u>22/19/14</u>	23/19/13
FLUID DEGRADA	ATION	method	limit/base	current	history1	history2



OIL ANALYSIS REPORT





CALA ISO 17025:2017 Accredited

Laboratory

Laboratory Sample No. Lab Number **Unique Number** Test Package

: WC0783691 . 02585847

: MAR 2

: 5654913

: WearCheck - C8-1175 Appleby Line, Burlington, ON L7L 5H9 Received : 28 Sep 2023 : 02 Oct 2023 Diagnosed

: Wes Davis Diagnostician

Canadian Coast Guard CCGS Martha L. Black, 101 Boul. Champlain, Depot 18

Quebec, QC CA G1K 7Y7

Contact: Chief Engineer marthalblackce@ccgs-ngcc.gc.ca T: (418)563-1735

To discuss this sample report, contact Customer Service at 1-800-268-2131. Test denoted (*) outside scope of accreditation, (m) method modified, (e) tested at external lab. Validity of results and interpretation are based on the sample and information as supplied.

F: