




PROBLEM SUMMARY

Sample Rating Trend


VISUAL METAL

Area
PLANT 7
 Machine Id
AHS SLT
 Component
1 Hydraulic System
 Fluid
COMMERCIAL OIL LUBRIKO AW 46 (100 LTR)



COMPONENT CONDITION SUMMARY


▲ Particle Trend



RECOMMENDATION

We advise that you check all areas where contaminants can enter the system. We recommend you service the filters on this component. We recommend an early resample to monitor this condition. Please specify the component make and model with your next sample. We suspect that the abnormal contaminant(s) is the result of incorrect sampling technique. **DISCLAIMER:** Interpretation of results is based on the sample as received from the customer. The condition of the sample and the method of sampling cannot be verified.

PROBLEMATIC TEST RESULTS

Sample Status				ABNORMAL	---	---
Particles >4µm		ASTM D7647	>5000	▲ 17061	---	---
Oil Cleanliness		ISO 4406 (c)	>19/17/14	▲ 21/17/9	---	---
White Metal	scalar	Visual*	NONE	▲ VLITE	---	---
Debris	scalar	Visual*	NONE	▲ VLITE	---	---
PrtFilter					no image	no image

Customer Id: TAYSTO
 Sample No.: WC0754607
 Lab Number: 02590007
 Test Package: IND 2



To manage this report scan the QR code

To discuss the diagnosis or test data:
 Kevin Marson +1 (289)291-4644 x4644
Kevin.Marson@wearcheck.com

To change component or sample information:
 Gloria Gonzalez +1 (289)291-4643 x4643
gloria.gonzalez@wearcheck.com





RECOMMENDED ACTIONS

Action	Status	Date	Done By	Description
Change Filter	---	---	?	We recommend you service the filters on this component.
Resample	---	---	?	We recommend an early resample to monitor this condition.
Alert	---	---	?	We suspect that the abnormal contaminant(s) is the result of incorrect sampling technique. DISCLAIMER: Interpretation of results is based on the sample as received from the customer. The condition of the sample and the method of sampling cannot be verified.
Information Required	---	---	?	Please specify the component make and model with your next sample.
Check Dirt Access	---	---	?	We advise that you check all areas where contaminants can enter the system.

HISTORICAL DIAGNOSIS



OIL ANALYSIS REPORT







VISUAL	method	limit/base	current	history1	history2
White Metal	scalar	Visual*	NONE	▲ VLITE	---
Yellow Metal	scalar	Visual*	NONE	NONE	---
Precipitate	scalar	Visual*	NONE	NONE	---
Silt	scalar	Visual*	NONE	NONE	---
Debris	scalar	Visual*	NONE	▲ VLITE	---
Sand/Dirt	scalar	Visual*	NONE	NONE	---
Appearance	scalar	Visual*	NORML	NORML	---
Odor	scalar	Visual*	NORML	NORML	---
Emulsified Water	scalar	Visual*	>0.1	NEG	---
Free Water	scalar	Visual*		NEG	---

FLUID PROPERTIES	method	limit/base	current	history1	history2
Visc @ 40°C	cSt	ASTM D7279(m)	46	43.3	---

SAMPLE IMAGES	method	limit/base	current	history1	history2
Color				no image	no image
Bottom				no image	no image
PrtFilter				no image	no image

GRAPHS



Laboratory : WearCheck - C8-1175 Appleby Line, Burlington, ON L7L 5H9
Sample No. : WC0754607 **Received** : 18 Oct 2023
Lab Number : 02590007 **Diagnosed** : 20 Oct 2023
Unique Number : 5659073 **Diagnostician** : Kevin Marson
Test Package : IND 2 (Additional Tests: Bottom, BottomAnalysis, FilterPatch, PrtFilter)

TAYLOR STEEL
 484 ARVIN AVE
 STONEY CREEK, ON
 CA L8E 2M9
 Contact: George Campanaro
 gcampanaro@taylorsteel.com
 T: (905)662-4925
 F: (905)662-4928

To discuss this sample report, contact Customer Service at 1-800-268-2131.
 Test denoted (*) outside scope of accreditation, (m) method modified, (e) tested at external lab.
 Validity of results and interpretation are based on the sample and information as supplied.