


PROBLEM SUMMARY

^{Area} [7898668]


TINKER OMEGA PH82503 TRAY STAKER (S/N MIP-1224)

Hydraulic System

CASTROL HYSPIN DHV 46 (225 LTR)



COMPONENT CONDITION SUMMARY



RECOMMENDATION

We advise that you perform a filter service, and use off-line filtration to improve the cleanliness of the system fluid. We recommend an early resample to monitor this condition.

PROBLEMATIC TEST RESULTS								
Sample Status			ABNORMAL	ABNORMAL	SEVERE			
Particles >4µm	ASTM D7647 >	-5000	<u> </u>	<u> </u>	▲ 34096			
Particles >6μm	ASTM D7647 >	1300	8034	4340	13426			
Particles >14μm	ASTM D7647 >	160	<u> </u>	<u>▲</u> 341	9 07			
Particles >21μm	ASTM D7647 >	40	<u> </u>	<u></u> 64	<u>196</u>			
Oil Cleanliness	ISO 4406 (c) >	19/17/14	<u>22/20/16</u>	<u>^</u> 21/19/16	22/21/17			

Customer Id: ESCPOR **Sample No.:** WC0741313 Lab Number: 02602851 Test Package: IND 2



To manage this report scan the QR code

To discuss the diagnosis or test data: Wes Davis +1 905-569-8600 x223 wesd@wearcheck.ca

To change component or sample information: Gloria Gonzalez +1 (289)291-4643 x4643 gloria.gonzalez@wearcheck.com

RECOMMENDED ACTIONS

Action	Status	Date	Done By	Description
Change Filter			?	We advise that you perform a filter service, and use off-line filtration to improve the cleanliness of the system fluid.
Resample			?	We recommend an early resample to monitor this condition.
Filter Fluid			?	We advise that you perform a filter service, and use off-line filtration to improve the cleanliness of the system fluid.

HISTORICAL DIAGNOSIS

01 Sep 2023 Diag: Wes Davis

ISO



We recommend you service the filters on this component. We recommend an early resample to monitor this condition. All component wear rates are normal. There is a moderate amount of silt (particulates < 14 microns in size) present in the oil. The AN level is acceptable for this fluid. The oil is still serviceable provided that the contaminant(s) can be reduced to acceptable levels.



ISO



15 May 2023 Diag: Kevin Marson

We advise that you check all areas where contaminants can enter the system. We advise that you perform a filter service, and use off-line filtration to improve the cleanliness of the system fluid. The air breather requires service. If unrated, we recommend that you replace with a suitable micron rated and/or desiccant air breather. If rated, we recommend that you service/replace the breather. Resample in 30-45 days to monitor this situation. We suspect that the abnormal contaminant(s) is the result of incorrect sampling technique. DISCLAIMER: Interpretation of results is based on the sample as received from the customer. The condition of the sample and the method of sampling cannot be verified.All component wear rates are normal. There is a high amount of particulates (2 to 100 microns in size) present in the oil. Light concentration of visible dirt/debris present in the oil. The AN level is acceptable for this fluid. The oil is still serviceable provided that the contaminant(s) can be reduced to acceptable levels.



17 Feb 2023 Diag: Wes Davis



We advise that you check all areas where contaminants can enter the system. We advise that you perform a filter service, and use off-line filtration to improve the cleanliness of the system fluid. The air breather requires service. If unrated, we recommend that you replace with a suitable micron rated and/or desiccant air breather. If rated, we recommend that you service/replace the breather. Resample in 30-45 days to monitor this situation. All component wear rates are normal. There is a high amount of particulates (2 to 100 microns in size) present in the oil. The AN level is acceptable for this fluid. The oil is still serviceable provided that the contaminant(s) can be reduced to acceptable levels.






OIL ANALYSIS REPORT

Area [7898668]

TINKER OMEGA PH82503 TRAY STAKER (S/N MIP-1224)

Hydraulic System

CASTROL HYSPIN DHV 46 (225 LTR)





DIAGNOSIS

Recommendation

We advise that you perform a filter service, and use off-line filtration to improve the cleanliness of the system fluid. We recommend an early resample to monitor this condition.

Wear

All component wear rates are normal.

Contamination

There is a moderate amount of particulates (2 to 100 microns in size) present in the oil.

Fluid Condition

The AN level is acceptable for this fluid. The oil is still serviceable provided that the contaminant(s) can be reduced to acceptable levels.

		Jul2022	Jan 2023 Feb 2023	May2023 Sep2023	Nov2023	
SAMPLE INFOR	MATION	method	limit/base	current	history1	history2
Sample Number		Client Info		WC0741313	WC0741319	WC0741329
Sample Date		Client Info		26 Nov 2023	01 Sep 2023	15 May 2023
Machine Age	hrs	Client Info		0	0	0
Oil Age	hrs	Client Info		0	0	0
Oil Changed		Client Info		N/A	N/A	N/A
Sample Status				ABNORMAL	ABNORMAL	SEVERE
CONTAMINATIO	N	method	limit/base	current	history1	history2
Water		WC Method	>0.05	NEG	NEG	NEG
WEAR METALS		method	limit/base	current	history1	history2
Iron	ppm	ASTM D5185(m)	>20	<1	3	<1
Chromium	ppm	ASTM D5185(m)	>20	0	0	0
Nickel	ppm	ASTM D5185(m)	>20	0	0	<1
Titanium	ppm	ASTM D5185(m)		0	0	0
Silver	ppm	ASTM D5185(m)		<1	<1	0
Aluminum	ppm	ASTM D5185(m)	>20	<1	<1	<1
Lead	ppm	ASTM D5185(m)	>20	0	<1	0
Copper	ppm	ASTM D5185(m)	>20	<1	1	<1
Tin	ppm	ASTM D5185(m)	>20	0	0	0
Antimony	ppm	ASTM D5185(m)		0	0	0
Vanadium	ppm	ASTM D5185(m)		0	0	0
Beryllium	ppm	ASTM D5185(m)		0	0	0
Cadmium	ppm	ASTM D5185(m)		0	0	0
ADDITIVES		method	limit/base	current	history1	history2
Boron	ppm	ASTM D5185(m)		8	<1	7
Barium	ppm	ASTM D5185(m)		<1	<1	0
Molybdenum	ppm	ASTM D5185(m)		3	0	3
Manganese	ppm	ASTM D5185(m)		0	0	0
Magnesium	ppm	ASTM D5185(m)		22	<1	23
Calcium	ppm	ASTM D5185(m)		112	13	109
Phosphorus	ppm	ASTM D5185(m)		384	512	409
Zinc	ppm	ASTM D5185(m)		484	608	483
Sulfur	ppm	ASTM D5185(m)		1347	4147	1355
Lithium	ppm	ASTM D5185(m)		<1	<1	<1
CONTAMINANT	S	method	limit/base	current	history1	history2
Silicon	ppm	ASTM D5185(m)	>15	3	14	3
Sodium	ppm	ASTM D5185(m)		<1	<1	0
Potassium	ppm	ASTM D5185(m)	>20	0	0	<1
FLUID CLEANLI	NESS	method	limit/base	current	history1	history2
Particles >4µm		ASTM D7647	>5000	24869	<u> </u>	△ 34096
Particles >6µm		ASTM D7647	>1300	8034	4340	13426
Particles >14µm		ASTM D7647	>160	<u>▲</u> 571	△ 341	△ 907
Particles >21µm		ASTM D7647	>40	<u> </u>	△ 64	<u></u> 196
Particles >38µm		ASTM D7647	>10	5	4	5
Particles >71µm		ASTM D7647	>3	1	1	0
0' 0		100 4400 ()	10/17/14	A 00/00/40	A 04/40/40	00/04/47


ISO 4406 (c) >19/17/14 **22/20/16**

Oil Cleanliness

<u>\(21/19/16</u>



OIL ANALYSIS REPORT





CALA ISO 17025:2017 Accredited Laboratory

Laboratory Sample No. Lab Number Unique Number

: WC0741313 : 02602851 : 5695936 Test Package : IND 2

: WearCheck - C8-1175 Appleby Line, Burlington, ON L7L 5H9 Received : 13 Dec 2023 Diagnosed

: 14 Dec 2023 : Wes Davis Diagnostician

ESCO LTD. P.O.BOX 270, 185 HOPE STREET SOUTH

PORT HOPE, ON CA L1A 3W4 Contact: Paul Dundas

paul.dundas@mail.weir T: (647)725-8153

To discuss this sample report, contact Customer Service at 1-800-268-2131.

Test denoted (*) outside scope of accreditation, (m) method modified, (e) tested at external lab. Validity of results and interpretation are based on the sample and information as supplied. F: (905)885-7600