




OIL ANALYSIS REPORT

Sample Rating Trend

NORMAL



Area
Kilian - K02400
 Machine Id
A2401030
 Component
Cutting Fluid
 Fluid
CHEM-ECOL CUTTING OIL 521 (--- GAL)

DIAGNOSIS

Recommendation

This is a baseline read-out on the submitted sample.

Wear

{not applicable}

Contamination

{not applicable}

Fluid Condition

{not applicable}

SAMPLE INFORMATION

	method	limit/base	current	history1	history2
Batch #	Client Info		2023 12 0260	---	---
Department	Client Info		Production	---	---
Sample From	Client Info		Machine	---	---
Production Stage	Client Info		Lab Reclaim	---	---
Sent to WC	Client Info		01/05/2024	---	---
Sample Number	Client Info		E30001115	---	---
Sample Date	Client Info		05 Jan 2024	---	---
Machine Age	hrs	Client Info	0	---	---
Oil Age	hrs	Client Info	0	---	---
Oil Changed	Client Info		N/A	---	---
Sample Status			NORMAL	---	---

CONTAMINATION

	method	limit/base	current	history1	history2
Water	WC Method		NEG	---	---

SULFUR CONTENT

	method	limit/base	current	history1	history2
Total Sulfur	%	ASTM D1552	1.10	---	---
Total Chlorine	%	ASTM D808	0.70	---	---
Active Sulfur	%	ASTM D1662	0.12	---	---

SAMPLE IMAGES

	method	limit/base	current	history1	history2
Color				<i>no image</i>	<i>no image</i>
Bottom				<i>no image</i>	<i>no image</i>

OIL ANALYSIS REPORT

GRAPHS



ISO 17025:2017
Accredited
Laboratory

Laboratory : WearCheck - C8-1175 Appleby Line, Burlington, ON L7L 5H9
Sample No. : E30001115
Lab Number : 02607640
Unique Number : 5708726
Test Package : TEST (Additional Tests: Chlorine-Total, Sulphur-Active, Sulphur-Total)

Environmental 360 Solutions Ltd.
640 Victoria Street
Cobourg, ON
CA K9A 5H5
Contact: Tatiana Sorkina
tsorkina@e360s.ca
T: (800)263-3939
F: (905)373-4950

*To discuss this sample report, contact Customer Service at 1-905-372-2251.
Test denoted (*) outside scope of accreditation, (m) method modified, (e) tested at external lab.
Validity of results and interpretation are based on the sample and information as supplied.*