

PROBLEM SUMMARY

Sample Rating Trend




10580137 ROCK BREAKER

Component


Hydraulic System


SHELL TELLUS 68 (--- GAL)





COMPONENT CONDITION SUMMARY





RECOMMENDATION

We advise that you check all areas where contaminants can enter the system. We advise that you perform a filter service, and use off-line filtration to improve the cleanliness of the system fluid. The air breather requires service. If unrated, we recommend that you replace with a suitable micron rated and/or desiccant air breather. If rated, we recommend that you service/replace the breather. Resample in 30-45 days to monitor this situation. NOTE: Please provide information regarding reservoir capacity, filter type and micron rating with next sample.

PROBLEMATIC	TEST RESU	LTS
-------------	-----------	-----

Sample Status			SEVERE	SEVERE	SEVERE
Particles >4µm	ASTM D7647	>5000	1 72556	▲ 68719	46550
Particles >6µm	ASTM D7647	>1300	21994	1 5310	1 3968
Particles >14µm	ASTM D7647	>160	1707	<u>▲</u> 1022	△ 697
Particles >21μm	ASTM D7647	>40	197	<u> </u>	77
Oil Cleanliness	ISO 4406 (c)	>19/17/14	23/22/18	2 3/21/17	2 3/21/17

Customer Id: INCOCOLE **Sample No.:** WC0811772 Lab Number: 02624681 Test Package: IND 2



To manage this report scan the QR code

To discuss the diagnosis or test data: Kevin Marson +1 (289)291-4644 x4644 Kevin.Marson@wearcheck.com

To change component or sample information: Gloria Gonzalez +1 (289)291-4643 x4643 gloria.gonzalez@wearcheck.com

RECOMMENDED A	CTIONS			
Action	Status	Date	Done By	Description
Change Filter			?	We advise that you perform a filter service, and use off-line filtration to improve the cleanliness of the system fluid.
Resample			?	Resample in 30-45 days to monitor this situation.
Information Required			?	NOTE: Please provide information regarding reservoir capacity, filter type and micron rating with next sample.
Check Breathers			?	The air breather requires service. If unrated, we recommend that you replace with a suitable micron rated and/or desiccant air breather. If rated, we recommend that you service/replace the breather.
Check Dirt Access			?	We advise that you check all areas where contaminants can enter the system.
Filter Fluid			?	We advise that you perform a filter service, and use off-line filtration to improve the cleanliness of the system fluid.

HISTORICAL DIAGNOSIS

24 Feb 2024 Diag: Kevin Marson

ISO

Check seals and/or filters for points of contaminant entry. We advise that you check all areas where contaminants can enter the system. We advise that you check for visible metal particles in the oil. The air breather requires service. If unrated, we recommend that you replace with a suitable micron rated and/or desiccant air breather. If rated, we recommend that you service/replace the breather. We advise that you perform a filter service, and use off-line filtration to improve the cleanliness of the system fluid. Resample in 30-45 days to monitor this situation. NOTE: Please provide information regarding reservoir capacity, filter type and micron rating with next sample. We suspect that the abnormal contaminant(s) is the result of incorrect sampling technique. DISCLAIMER: Interpretation of results is based on the sample as received from the customer. The condition of the sample and the method of sampling cannot be verified.Light concentration of visible metal present. There is a high amount of silt (particulates < 14 microns in size) present in the oil. Light concentration of visible dirt/debris present in the oil. The AN level is acceptable for this fluid. The oil is no longer serviceable as a result of the abnormal and/or severe wear.





15 Nov 2023 Diag: Kevin Marson
Check seals and/or filters for points of contaminant entry. We advise that you check all areas where contaminants can enter the system. We advise that you check for visible metal particles in the oil. The air breather requires service. If unrated, we recommend that you replace with a suitable micron rated and/or desiccant air breather. If rated, we recommend that you service/replace the breather. We advise that you perform a filter service, and use off-line filtration to improve the cleanliness of the system fluid. Resample in 30-45 days to monitor this situation. NOTE: Please provide information regarding reservoir capacity, filter type and micron rating with next sample. We suspect that the abnormal contaminant(s) is the result of incorrect sampling technique. DISCLAIMER: Interpretation of results is based on the sample as received from the customer. The condition of the sample and the method of sampling cannot be verified.Light concentration of visible metal present. There is a high amount of silt (particulates < 14 microns in size) present in the oil. Light concentration of visible dirt/debris present in the oil. The AN level is acceptable for this fluid. The oil is no longer serviceable as a result of the abnormal and/or severe wear.



18 Oct 2023 Diag: Kevin Marson





We advise that you perform a filter service, and use off-line filtration to improve the cleanliness of the system fluid. We recommend an early resample to monitor this condition. NOTE: Please provide information regarding reservoir capacity, filter type and micron rating with next sample. Iron ppm levels are noted. The low ferrous density (PQ) index indicates the wear metal levels are due to corrosion. All other component wear rates are normal. There is a moderate amount of particulates (2 to 100 microns in size) present in the oil. The AN level is acceptable for this fluid. The oil is still serviceable provided that the contaminant(s) can be reduced to acceptable levels.





OIL ANALYSIS REPORT

Sample Rating Trend



10580137 ROCK BREAKER

Hydraulic System

SHELL TELLUS 68 (--- GAL)

DIAGNOSIS

Recommendation

We advise that you check all areas where contaminants can enter the system. We advise that you perform a filter service, and use off-line filtration to improve the cleanliness of the system fluid. The air breather requires service. If unrated, we recommend that you replace with a suitable micron rated and/or desiccant air breather. If rated, we recommend that you service/replace the breather. Resample in 30-45 days to monitor this situation. NOTE: Please provide information regarding reservoir capacity, filter type and micron rating with next sample.

Wear

All component wear rates are normal.

Contamination

There is a high amount of particulates (2 to 100 microns in size) present in the oil.


Fluid Condition

The AN level is acceptable for this fluid. The oil is still serviceable provided that the contaminant(s) can be reduced to acceptable levels.

SAMPLE INFORMATION
Sample Date Client Info 19 Mar 2024 24 Feb 2024 15 Nov 2023 Machine Age mths Client Info 0 0 0 Did Age mths Client Info 0 0 0 0 Did Changed Client Info N/A N/A N/A N/A Sample Status SEVERE SEVERE SEVERE CONTAMINATION method limit/base current history1 history2 Vater WC Method >0.05 NEG NEG NEG WEAR METALS method limit/base current history1 history2 O
Machine Age mths Client Info 0 0 0 Dil Age mths Client Info 0 0 0 Dil Changed Client Info N/A N/A N/A Sample Status SEVERE SEVERE SEVERE CONTAMINATION method limit/base current history1 history2 Vater WC Method >0.05 NEG NEG NEG VEAR METALS method limit/base current history1 history2 VEAR METALS method limi
Dil Age
Contample Client Info N/A N/A N/A N/A Sample Status Severe Severe
SEVERE S
CONTAMINATION method limit/base current history1 history2 Vater WC Method >0.05 NEG NEG NEG WEAR METALS method limit/base current history1 history2 PQ ASTM D8184* 0 0 PQ ASTM D5185(m) >20 22 16 27 Chromium ppm ASTM D5185(m) >20 <1
Water WC Method >0.05 NEG NEG NEG WEAR METALS method limit/base current history1 history2 PQ ASTM D8184* 0 0 con ppm ASTM D5185(m) >20 22 16 27 Chromium ppm ASTM D5185(m) >20 <1 1 1 Lickel ppm ASTM D5185(m) >20 0 <1 <1 Litanium ppm ASTM D5185(m) 0 0 0 <1 Silver ppm ASTM D5185(m) >20 <1 <1 <1 Lead ppm ASTM D5185(m) >20 <1 <1 <1 Lead ppm ASTM D5185(m) >20 <1 <1 <1 Copper ppm ASTM D5185(m) >20 0 0 0 Christianium ppm ASTM D5185(m) 0 0 0 0
WEAR METALS method limit/base current history1 history2 PQ ASTM D8184* 0 0 Pon ppm ASTM D5185(m) >20 22 16 27 Chromium ppm ASTM D5185(m) >20 <1 1 1 Chromium ppm ASTM D5185(m) >20 0 <1 <1 Clickel ppm ASTM D5185(m) 0 0 0 0 Cliver ppm ASTM D5185(m) 0 0 <1 <1 ASIMURIUM ppm ASTM D5185(m) >20 <1 <1 <1 Acaded ppm ASTM D5185(m) >20 <1 <1 1 Acaded ppm ASTM D5185(m) >20 <1 <1 1 Acaded ppm ASTM D5185(m) >20 0 0 0 Acaded ppm ASTM D5185(m) 0 0 0 0 </th
ASTM D8184* O O Fron ppm ASTM D5185(m) >20 22 16 27 Chromium ppm ASTM D5185(m) >20 <1 1 1 1 ASTM D5185(m) >20 C1 1 1 1 ASTM D5185(m) >20 O C1 C1 C1 C1 C1 Citanium ppm ASTM D5185(m) O O O Citanium ppm ASTM D5185(m) O O O Citanium ppm ASTM D5185(m) >20 C1 C1 C1 C1 Copper ppm ASTM D5185(m) >20 C1 C1 C1 C1 Copper ppm ASTM D5185(m) >20 C1 C1 C1 C1 Copper ppm ASTM D5185(m) >20 C1 C1 C1 C1 Copper ppm ASTM D5185(m) >20 O O O Copper ppm ASTM D5185(m) >20 O O Continony ppm ASTM D5185(m) >20 O O Continony ppm ASTM D5185(m) O O O
Description
Chromium ppm ASTM D5185(m) >20 <1 1 1 1
Dickel ppm ASTM D5185(m) >20 0 <1 <1 <1 <1 <1 <1 <1
Fitanium ppm ASTM D5185(m) 0 0 0 Silver ppm ASTM D5185(m) 0 0 <1 Aluminum ppm ASTM D5185(m) >20 <1 <1 <1 Lead ppm ASTM D5185(m) >20 0 <1 0 Copper ppm ASTM D5185(m) >20 <1 <1 1 Copper ppm ASTM D5185(m) >20 0 0 0 Variation ppm ASTM D5185(m) 0 0 0 Candium ppm ASTM D5185(m) 0 0 0 Cadmium ppm ASTM D5185(m) 0 0 0
Deadmium Deadmium
ASTM D5185(m) >20 <1 <1 <1 <1 <1 <1 <1 <
pead ppm ASTM D5185(m) >20 0 <1 0 Copper ppm ASTM D5185(m) >20 <1 <1 1 rin ppm ASTM D5185(m) >20 0 0 0 vantimony ppm ASTM D5185(m) 0 0 0 vanadium ppm ASTM D5185(m) 0 0 0 Beryllium ppm ASTM D5185(m) 0 0 0 Cadmium ppm ASTM D5185(m) 0 0 0
Copper ppm ASTM D5185(m) >20 <1 <1 1 Cin ppm ASTM D5185(m) >20 0 0 0 Vantimony ppm ASTM D5185(m) 0 0 0 Vanadium ppm ASTM D5185(m) 0 0 0 Beryllium ppm ASTM D5185(m) 0 0 0 Cadmium ppm ASTM D5185(m) 0 0 0
Fin ppm ASTM D5185(m) >20 0 0 0 Intimony ppm ASTM D5185(m) 0 0 0 0 Vanadium ppm ASTM D5185(m) 0 0 0 0 Beryllium ppm ASTM D5185(m) 0 0 0 Cadmium ppm ASTM D5185(m) 0 0 0
Antimony ppm ASTM D5185(m) 0 0 0 0 Vanadium ppm ASTM D5185(m) 0 0 0 Beryllium ppm ASTM D5185(m) 0 0 0 Cadmium ppm ASTM D5185(m) 0 0 0
Vanadium ppm ASTM D5185(m) 0 0 0 Beryllium ppm ASTM D5185(m) 0 0 0 Cadmium ppm ASTM D5185(m) 0 0 0
Beryllium ppm ASTM D5185(m) 0 0 0 Cadmium ppm ASTM D5185(m) 0 0 0
Cadmium ppm ASTM D5185(m) 0 0
ADDITIVES method limit/base current history1 history2
Boron ppm ASTM D5185(m) <1 0 <1
Barium ppm ASTM D5185(m) 0 0 <1
Nolybdenum ppm ASTM D5185(m) 0 0 0
Manganese ppm ASTM D5185(m) 0 0
Magnesium ppm ASTM D5185(m) 11 67 67 67
Calcium ppm ASTM D5185(m) 39 13 14 14
Phosphorus ppm ASTM D5185(m) 260 288 297 287
Zinc ppm ASTM D5185(m) 279 355 348 349
Sulfur ppm ASTM D5185(m) 2109 658 710 656
ppm Asimusios(iii) 2109 030 710 030
ithium ppm ASTM D5185(m) <1 <1 <1
[F]
ithium ppm ASTM D5185(m) <1 <1 <1
ithium ppm ASTM D5185(m) <1 <1 <1 CONTAMINANTS method limit/base current history1 history2



OIL ANALYSIS REPORT





CALA ISO 17025:2017 Accredited

Laboratory Sample No. Lab Number

: WC0811772

: 02624681 Unique Number : 5749800

Received **Tested** Diagnosed Test Package : IND 2 (Additional Tests: PQ)

: 26 Mar 2024 · 27 Mar 2024 : 27 Mar 2024 - Kevin Marson

COLEMAN MINE (PLANT 10), 117 Mine Road

LEVACK, ON CA P0M 2C0 Contact: Ryan Davies ryan.davies@vale.com T: (705)682-8952

To discuss this sample report, contact Customer Service at 1-800-268-2131. Test denoted (*) outside scope of accreditation, (m) method modified, (e) tested at external lab. Validity of results and interpretation are based on the sample and information as supplied.

Contact/Location: Ryan Davies - INCOCOLE

F: (705)966-4114