

OIL ANALYSIS REPORT

Iron

Nickel

Silver

Lead

Tin

Boron

Zinc

Sulfur

Silicon

DOMTAR 211-411-1 [GTT224-445 DOMTAR] CARRIER DOMTAR 211-411-1

Chiller

Fluid **REFRIG COMP OIL ISO 32 (--- GAL)**

DIAGNOSIS

Recommendation

Resample at the next service interval to monitor. Please specify the brand, type, and viscosity of the oil on your next sample.

Wear


All component wear rates are normal.

Contamination

The water content is negligible. There is no indication of any contamination in the oil.

Fluid Condition

The AN level is acceptable for this fluid. The condition of the oil is suitable for further service.



Sample Rating Trend

NORMAL

Potassium	ppm	ASTM D5185(m)	>20	0		
ppm Water	ppm	ASTM D6304*	>100	22		
FLUID DEGRADA	TION	method	limit/base	current	history1	history2
Acid Number (AN)	mg KOH/g	ASTM D974*	0.10	0.03		



OIL ANALYSIS REPORT

VISUAL		method	limit/base	current	history1	history2
White Metal	scalar	Visual*	NONE	VLITE		
Yellow Metal	scalar	Visual*	NONE	NONE		
Precipitate	scalar	Visual*	NONE	NONE		
Silt	scalar	Visual*	NONE	NONE		
Debris	scalar	Visual*	NONE	NONE		
Sand/Dirt	scalar	Visual*	NONE	VLITE		
Appearance	scalar	Visual*	NORML	NORML		
Odor	scalar	Visual*	NORML	NORML		
FLUID PROPERTIES		method	limit/base	current	history1	history2
Visc @ 40°C	cSt	ASTM D7279(m)	32	31.5		
SAMPLE IMAGES		method	limit/base	current	history1	history2
Color					no image	no image
Bottom					no image	no image



Sample No. : GTT Received : 14 Jun 2024 4704 boul Bertrand Lab Number : 02642208 Tested : 24 Jun 2024 Unique Number : 5799747 Diagnosed : 24 Jun 2024 - Bill Quesnel Test Package : IND 2 (Additional Tests: KV40) Contact: Service Manager To discuss this sample report, contact Customer Service at 1-905-847-9300 Ext 26. Test denoted (*) outside scope of accreditation, (m) method modified, (e) tested at external lab. Damages: Seller shall in no event be liable for special, incidental, or consequential damages, of a commercial nature, resulting from any cause.

Report Id: GTT0000040 [WCAMIS] 02642208 (Generated: 06/24/2024 12:18:44) Rev: 1

Contact/Location: Service Manager - GTT0000040 Page 2 of 2

Bridair Inc.

Rock Forest, QC

CA J1N 2B1

T:

F: