


# **OIL ANALYSIS REPORT**

Sample Rating Trend



Machine Id M/C 509 Component Unknown Component {not provided} (--- GAL)

#### Recommendation

This is a baseline read-out on the submitted sample.


### Contamination

Water present at 93.8%.

SAMPLE INFORM	MOITAN	method	limit/base	current	history1	history2
Sample Number		Client Info		PP		
Sample Date		Client Info		14 Jul 2024		
Machine Age	hrs	Client Info		0		
Oil Age	hrs	Client Info		0		
Oil Changed		Client Info		N/A		
Sample Status				NORMAL		
CONTAMINANTS		method	limit/base	current	history1	history2
Water	%	ASTM D6304*		93.8		
ppm Water	ppm	ASTM D6304*		938000		
VISUAL		method	limit/base	current	history1	history2
White Metal	scalar	Visual*	NONE	NONE		
Yellow Metal	scalar	Visual*	NONE	NONE		
Precipitate	scalar	Visual*	NONE	NONE		
Silt	scalar	Visual*	NONE	NONE		
Debris	scalar	Visual*	NONE	NONE		
Sand/Dirt	scalar	Visual*	NONE	NONE		
Appearance	scalar	Visual*	NORML	NORML		
Odor	scalar	Visual*	NORML	NORML		
SAMPLE IMAGES	;	method	limit/base	current	history1	history2
Color					no image	no image
Bottom				0	no image	no image



## **OIL ANALYSIS REPORT**





CALA ISO 17025:2017 Accredited Laboratory

Laboratory Sample No.

Lab Number : 02647978 Unique Number : 5813530 Test Package : TEST ( Additional Tests: KF )

: WearCheck - C8-1175 Appleby Line, Burlington, ON L7L 5H9 : PP

To discuss this sample report, contact Customer Service at 1-800-268-2131.

Received **Tested** Diagnosed

: 15 Jul 2024 : 16 Jul 2024 : 17 Jul 2024 - Kevin Marson

**Powercor Manufacturing - Linamar** 545 Elmira Road Guelph, ON CA N1K 1C2 Contact: Manthan Rathi

manthan.rathi@linamar.com T: (226)326-0125 F: (226)326-0124

Test denoted (\*) outside scope of accreditation, (m) method modified, (e) tested at external lab. Validity of results and interpretation are based on the sample and information as supplied.