VOLVO

FUEL REPORT

Sample Rating Trend

NORMAL

Area [SWA305799 ESPERAZA] Machine Id TORO TX1000 412678973 Component

Diesel Fuel Fluid NOT GIVEN (--- GAL)

DIAGNOSIS

Recommendation

This is a baseline read-out on the submitted sample. No corrective action is recommended at this time.

Corrosion

All metal levels are normal indicating no corrosion in the system.

Contaminants

The water content is negligible. There is no indication of any contamination in the fuel.

Fuel Condition

The condition of the fuel is acceptable for the time in service.


the second s
2023
2023





SAMPLE INFORM	1ATION	method	limit/base	current	history1	history2
Sample Number		Client Info		VCP420191	VCP419504	
Sample Date		Client Info		11 Jul 2023	10 Jul 2023	
Machine Age	hrs	Client Info		186	186	
Sample Status				NORMAL	NORMAL	
PHYSICAL PROP	ERTIES	method	limit/base	current	history1	history2
Visc @ 40°C	cSt	ASTM D445		2.95	2.95	
SULFUR CONTEI	NT	method	limit/base	current	history1	history2
Sulfur	ppm	ASTM D5185m		0	0	
CONTAMINANTS		method	limit/base	current	history1	history2
Silicon	ppm	ASTM D5185m	<1.0	<1	<1	
Sodium	ppm	ASTM D5185m	<0.1	0	0	
Potassium	ppm	ASTM D5185m	<0.1	1	<1	
Water	%	ASTM D6304	<0.05	0.011	0.012	
ppm Water	ppm	ASTM D6304	<500	118.9	121.5	
HEAVY METALS		method	limit/base	current	history1	history2
Aluminum	ppm	ASTM D5185m	<0.1	0	0	
Nickel	ppm	ASTM D5185m	<0.1	<1	<1	
Lead	ppm	ASTM D5185m	<0.1	0	0	
Vanadium	ppm	ASTM D5185m	<0.1	0	0	
Iron	ppm	ASTM D5185m	<0.1	<1	0	
Calcium	ppm	ASTM D5185m	<0.1	0	0	
Magnesium	ppm	ASTM D5185m	<0.1	0	0	
Phosphorus	ppm	ASTM D5185m	<0.1	0	0	
Zinc	ppm	ASTM D5185m	<0.1	0	0	
SAMPLE IMAGES	\$	method	limit/base	current	history1	history2
Color						no image
Bottom						no image



FUEL REPORT







Contact/Location: DAVE ENG - VOLVO8885