# VOLVO

# **FUEL REPORT**

### Sample Rating Trend

NORMAL

# [X47254] Machine Id TADANO GR550XL-3 542059

Component Diesel Fuel Fluid NOT GIVEN (--- GAL)

## DIAGNOSIS

#### Recommendation

This is a baseline read-out on the submitted sample.

### Corrosion


All metal levels are normal indicating no corrosion in the system.

#### Contaminants

The water content is negligible. There is no indication of any contamination in the fuel.

### **Fuel Condition**

The condition of the fuel is acceptable for the time in service.








SAMPLE INFORMATION method VCP416483 VCP351103 Client Info VCP378222 Sample Number Client Info 13 Jul 2023 Sample Date 17 Feb 2023 13 Apr 2022 2027 Machine Age hrs **Client Info** 1790 567 Sample Status NORMAL NORMAL NORMAL Visc @ 40°C cSt ASTM D445 2.59 2.46 2.98 SULFUR CONTENT Sulfur ASTM D5185m 0 6 <1 ppm 0 0 Silicon ppm ASTM D5185m <1.0 <1 ASTM D5185m <0.1 0 0 Sodium <1 ppm Potassium ppm ASTM D5185m < 0.1 <1 <1 0 Water % ASTM D6304 <0.05 0.003 0.006 0.002 ppm Water ppm ASTM D6304 <500 37.2 62.5 23.0 Aluminum ppm ASTM D5185m < 0.1 <1 0 0 Nickel 0 0 0 ppm ASTM D5185m <0.1 0 0 0 Lead ASTM D5185m <0.1 ppm Vanadium <0.1 0 0 ppm ASTM D5185m <1 0 0 Iron ppm ASTM D5185m < 0.1 0 Calcium ppm ASTM D5185m <0.1 0 6 2 < 0.1 2 0 Magnesium ppm ASTM D5185m <1 0 0 4 Phosphorus ppm ASTM D5185m <0.1 3 0 Zinc ASTM D5185m <0.1 0 ppm SAMPLE IMAGES Color Bottom



# **FUEL REPORT**







Contact/Location: TINA LEDOUX - VOLVO6244