


## **FUEL REPORT**

# Area [225089 JMK] Machine Id VOLVO L90H 625422



Component
Diesel Fuel
Fluid
NOT GIVEN (--- GAL)





### **DIAGNOSIS**

#### Recommendation

We advise that you check all areas where dirt can enter the system. We recommend you service the filters on this component if applicable. We advise that you inspect for the source(s) of rust.

#### Corrosion

Iron ppm levels are abnormal. Aluminum ppm levels are noted. Moderate concentration of visible metal present rust.

#### Contaminants

Moderate concentration of visible dirt/debris present in the fuel. Elemental levels of silicon (Si) and aluminum (Al) indicate possible alumina-silicate (coarse dirt) ingress.


#### **Fuel Condition**

{not applicable}


				Aug2023		
SAMPLE INFORM	MATION	method	limit/base	current	history1	history2
Sample Number		Client Info		VCP426759		
Sample Date		Client Info		14 Aug 2023		
Machine Age	hrs	Client Info		11125		
Sample Status				ABNORMAL		
PHYSICAL PROP	ERTIES	method	limit/base	current	history1	history2
Visc @ 40°C	cSt	ASTM D445		3.27		
SULFUR CONTE	NT	method	limit/base	current	history1	history2
Sulfur	ppm	ASTM D5185m		0		
CONTAMINANTS		method	limit/base	current	history1	history2
Silicon	ppm	ASTM D5185m	<1.0	<b>4</b> 7		
Sodium	ppm	ASTM D5185m	< 0.1	2		
Potassium	ppm	ASTM D5185m	< 0.1	0		
Water	%	ASTM D6304	< 0.05	0.018		
ppm Water	ppm	ASTM D6304	< 500	187.3		
HEAVY METALS		method	limit/base	current	history1	history2
Aluminum	ppm	ASTM D5185m	< 0.1	<u>^</u> 6		
Nickel	ppm	ASTM D5185m	< 0.1	0		
Lead	ppm	ASTM D5185m	< 0.1	0		
Vanadium	ppm	ASTM D5185m	<0.1	<1		
Iron	ppm	ASTM D5185m	< 0.1	<u>^</u> 6		
Calcium	ppm	ASTM D5185m	<0.1	5		
Magnesium	ppm	ASTM D5185m	< 0.1	3		
Phosphorus	ppm	ASTM D5185m	<0.1	0		
Zinc	ppm	ASTM D5185m	< 0.1	<1		
SAMPLE IMAGES	3	method	limit/base	current	history1	history2
Color					no image	no image
Bottom					no image	no image



## **FUEL REPORT**



**GRAPHS** 



Laboratory Sample No. Lab Number Unique Number : 10619268

: VCP426759 : 05933997

Test Package : MOB 1 ( Additional Tests: KF )

: WearCheck USA - 501 Madison Ave., Cary, NC 27513 Received Diagnosed

: 24 Aug 2023 : 06 Sep 2023 Diagnostician : Doug Bogart

**PACWEST MACHINERY** 8207 SOUTH 216TH STREET

KENT, WA US 98032

Contact: T. GUSTIN tgustin@pacwestmachinery.com

T: (800)935-5933 F: (509)534-5286

To discuss this sample report, contact Customer Service at 1-800-237-1369. \* - Denotes test methods that are outside of the ISO 17025 scope of accreditation.

Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012)