

OIL ANALYSIS REPORT

OKLAHOMA/102/EG - DOZER 35.97L [OKLAHOMA^102^EG - DOZER]

Sample Rating Trend

NORMAL



DIAGNOSIS

Contamination

Fluid Condition


in service.

Wear

fluid

Componen Left Final Drive

MOBIL MOBILTRANS HD 50 (--- GAL)




Report Id: SHEWIC [WUSCAR] 06000755 (Generated: 11/13/2023 01:42:36) Rev: 1


Submitted By: BOBBY JONES



OIL ANALYSIS REPORT



SAMPLE IMAGES	method	limit/base	current	history1	history2
Color			no image	no image	no image
Bottom			no image	no image	no image
GRAPHS					



SHERWOOD CONSTRUCTION CO INC 3219 WEST MAY ST WICHITA, KS US 67213 Contact: DOUG KING doug.king@sherwood.net T: (316)617-3161 M 106:2012) F: x:





Laboratory Sample No.

Lab Number

Unique Number : 10729115

 Certificate L2367
 Test Package
 : CONST

 To discuss this sample report, contact Customer Service at 1-800-237-1369.
 *

 * - Denotes test methods that are outside of the ISO 17025 scope of accreditation.
 Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012)

: WC0726213

: 06000755

: WearCheck USA - 501 Madison Ave., Cary, NC 27513

: 07 Nov 2023

: 09 Nov 2023

Diagnostician : Don Baldridge

Received

Diagnosed

Page 2 of 2