


Area
Recycled Fiber
Machine Id
FILTER
Component
Filter
Fluid
{not provided} (--- GAL)



WEAR

The filter contained no appreciable wear particles. All filter wear levels are normal. filter patch is non-ferrous, image 1 consists of large non-ferrous particle, tested positive for Aluminum (wet chem). Image 2 consists of 10-20 ferrous rolling wear.