








Hilcorp Alaska, LLC


OIL ANALYSIS REPORT








VISUAL	method	limit/base	current	history1	history2
White Metal	scalar	*Visual	NONE	NONE	---
Yellow Metal	scalar	*Visual	NONE	NONE	---
Precipitate	scalar	*Visual	NONE	NONE	---
Silt	scalar	*Visual	NONE	NONE	---
Debris	scalar	*Visual	NONE	NONE	---
Sand/Dirt	scalar	*Visual	NONE	NONE	---
Appearance	scalar	*Visual	NORML	NORML	---
Odor	scalar	*Visual	NORML	NORML	---
Emulsified Water	scalar	*Visual	NEG	---	---
Free Water	scalar	*Visual	NEG	---	---

FLUID PROPERTIES	method	limit/base	current	history1	history2
Visc @ 40°C	cSt	ASTM D445	106	111.4	---
Visc @ 100°C	cSt	ASTM D445	14.9	15.2	---
Viscosity Index (VI)	Scale	ASTM D2270	146	142	---

SAMPLE IMAGES	method	limit/base	current	history1	history2
---------------	--------	------------	---------	----------	----------



GRAPHS



Certificate L2367

Laboratory : WearCheck USA - 501 Madison Ave., Cary, NC 27513

Sample No. : HLC0002882

Lab Number : 06204015

Unique Number : 11071476

Test Package : IND 2 (Additional Tests: FT-IR, KV100, PrtCount, VI)

To discuss this sample report, contact Customer Service at 1-800-237-1369.

* - Denotes test methods that are outside of the ISO 17025 scope of accreditation.

Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012)

Received : 07 Jun 2024

Tested : 13 Jun 2024

Diagnosed : 13 Jun 2024 - Jonathan Hester

HILCORP EXPLORATION ALASKA - MILNE POINT

1000 MILNE POINT RD

PRUDOE BAY, AK

US 99734

Contact: Evan Reilly

evan.reilly@hilcorp.com

T: (907)670-3231

F: x: