

## **OIL ANALYSIS REPORT**

### Area OUTSIDE HYDRAULIC 2070 PP02

Hydraulic System

KLUBER SUMMIT HYSYN FG 46 (40 GAL)

#### DIAGNOSIS

#### Recommendation

No corrective action is recommended at this time. Resample at the next service interval to monitor.

#### 🔺 Wear


The iron level is abnormal. All other component wear rates are normal.

#### Contamination

The amount and size of particulates present in the system are acceptable.

#### Fluid Condition

The AN level is acceptable for this fluid. The condition of the oil is acceptable for the time in service.



Sample Rating Trend

WEAR

Report Id: FLAMONNC [WUSCAR] 06218229 (Generated: 06/25/2024 19:44:15) Rev: 1

Contact/Leastion: CLL

Contact/Location: CHRISTOPHER JACKSON - FLAMONNC



articles ( 8 6 41

2

0

600 500

3000 Nater (1 3000

100

55


5

40

Aug20/1


\ug20/

# **OIL ANALYSIS REPORT**





Bottom



Report Id: FLAMONNC [WUSCAR] 06218229 (Generated: 06/25/2024 19:44:15) Rev: 1

Contact/Location: CHRISTOPHER JACKSON - FLAMONNC