


# **OIL ANALYSIS REPORT**



KANSAS/44/EG - LOADER 47.08L [KANSAS^44^EG - LOADER]

Rear Differential

MOBIL MOBILTRANS AST 30 (--- GAL)





### Recommendation

Resample at the next service interval to monitor.

All component wear rates are normal.

### Contamination

There is no indication of any contamination in the


## **Fluid Condition**

The condition of the oil is acceptable for the time in service.

history2
0779738
Nov 2023
46
46
inged
RMAL
history2
IEG
history2
.2
)
)
:1
)
1
)
)
)
history2
)
)
:1
0
107
035
247
181
history2
;
}
history2
IONE
IORML
IORML
IEG
FANSC
1E 1C 1C 1C 1C





# **OIL ANALYSIS REPORT**




FLUID PROPER	RTIES	method	limit/base	current	history1	history2
Visc @ 40°C	cSt	ASTM D445	57.6	105	107	193
SAMPLE IMAG	ES	method	limit/base	current	history1	history2
Color				no image	no image	no image
Bottom				no image	no image	no image

## **GRAPHS**











Certificate 12367

Laboratory

Lab Number : 06237169 Unique Number : 11126003

**Sample No.** : WC06237169

: WearCheck USA - 501 Madison Ave., Cary, NC 27513 Received : 15 Jul 2024 Tested : 17 Jul 2024

Diagnosed Test Package : CONST To discuss this sample report, contact Customer Service at 1-800-237-1369. SHERWOOD CONSTRUCTION CO INC

3219 WEST MAY ST WICHITA, KS US 67213

Contact: BILL ORCUTT

william.orcutt@wildcat.net T:

\* - Denotes test methods that are outside of the ISO 17025 scope of accreditation.

Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012)

: 17 Jul 2024 - Don Baldridge

F: