





Engine	#	%	+/-
Fuel	95	9.4%	-7.9%
Glycol	65	6.4%	+9.9%
Wear	32	3.2%	-3.4%
Degradation	17	1.7%	+9.9%

Hydraulic	#	%	+/-
ISO	77	57.5%	+57.5%
Viscosity	16	11.9%	+3.8%
Wear	12	9.0%	-7.2%
Visual_Metal	4	3.0%	+3.0%

Transmission	#	%	+/-
Dirt	1	16.7%	+16.7%
Wear	0	0%	-100%
Viscosity	0	0%	-100%
---	---	---	---

Other	#	%	+/-
ISO	3	100.0%	+100.0%
Viscosity	0	0%	-100%
---	---	---	---
---	---	---	---






Total	1011	100.0%	-146
Normal	809	80.0%	+8.3%
Abnormal	143	14.1%	-8.0%
Severe	59	5.8%	+4.4%

Total	134	100.0%	+35
Normal	36	26.9%	-47.8%
Abnormal	94	70.1%	+54.9%
Severe	4	3.0%	-7.1%

Total	6	100.0%	+6
Normal	5	83.3%	---
Abnormal	1	16.7%	---
Severe	0	0.0%	---

Total	3	100.0%	+0
Normal	0	0.0%	-100.0%
Abnormal	3	100.0%	+100.0%
Severe	0	0.0%	+0.0%



Location	Sampled	Not Sampled	Total	%
GFL Environmental - Region 1	159	623	782	20.3
GFL Environmental - Region 2	309	532	841	36.7
GFL Environmental - Region 3	200	399	599	33.4
GFL Environmental - Region 4	252	356	608	41.4
GFL Environmental - Region 5	153	483	636	24.1
Total Sample Conformance	1073	2393	3466	31.0