MOBIL LUBE 360 OIL DIAGNOSTICS

# OIL ANALYSIS REPORT

| | |
|---|---|
| WEAR | NORMAL |
| CONTAMINATION | NORMAL |
| FLUID CONDITION | NORMAL |

Machine Id
**351019**
Component
**Diesel Engine**
Fluid
**PETRO CANADA DURON SHP 15W40 (--- GAL)**

## RECOMMENDATION

Resample at the next service interval to monitor.

## WEAR

Metal levels are typical for a components first oil change.

## CONTAMINATION

There is no indication of any contamination in the oil.

## FLUID CONDITION

The condition of the oil is acceptable for the time in service.

| Test | UOM | Method | Limit/Abn | Current | History1 | History2 |
|---|---|---|---|---|---|---|
| Sample Number | | Client Info | | GFL0059106 | --- | --- |
| Sample Date | | Client Info | | 28 Jan 2024 | --- | --- |
| Machine Age | hrs | Client Info | | 600 | --- | --- |
| Oil Age | hrs | Client Info | | 600 | --- | --- |
| Filter Age | hrs | Client Info | | 600 | --- | --- |
| Oil Changed | | Client Info | | Changed | --- | --- |
| Filter Changed | | Client Info | | Changed | --- | --- |
| Sample Status | | | | NORMAL | --- | --- |
| Iron | ppm | ASTM D5185(m) | >80 | 68 | --- | --- |
| Chromium | ppm | ASTM D5185(m) | >5 | 2 | --- | --- |
| Nickel | ppm | ASTM D5185(m) | >2 | <1 | --- | --- |
| Titanium | ppm | ASTM D5185(m) | | 0 | --- | --- |
| Silver | ppm | ASTM D5185(m) | >3 | 0 | --- | --- |
| Aluminum | ppm | ASTM D5185(m) | >30 | 27 | --- | --- |
| Lead | ppm | ASTM D5185(m) | >30 | <1 | --- | --- |
| Copper | ppm | ASTM D5185(m) | >150 | 19 | --- | --- |
| Tin | ppm | ASTM D5185(m) | >5 | 0 | --- | --- |
| Vanadium | ppm | ASTM D5185(m) | | 0 | --- | --- |
| Silicon | ppm | ASTM D5185(m) | >20 | 7 | --- | --- |
| Potassium | ppm | ASTM D5185(m) | >20 | 18 | --- | --- |
| Fuel | | WC Method | >5 | <1.0 | --- | --- |
| Water | | WC Method | >0.2 | NEG | --- | --- |
| Glycol | % | ASTM D7922* | | 0.0 | --- | --- |
| Soot % | % | ASTM D7844* | >3 | 1.3 | --- | --- |
| Nitration | Abs/cm | ASTM D7624* | >20 | 13.9 | --- | --- |
| Sulfation | Abs/.1mm | ASTM D7415* | >30 | 26.0 | --- | --- |
| Emulsified Water | scalar | Visual* | >0.2 | NEG | --- | --- |
| Sodium | ppm | ASTM D5185(m) | | 2 | --- | --- |
| Boron | ppm | ASTM D5185(m) | 0 | 3 | --- | --- |
| Barium | ppm | ASTM D5185(m) | 0 | 0 | --- | --- |
| Molybdenum | ppm | ASTM D5185(m) | 60 | 58 | --- | --- |
| Manganese | ppm | ASTM D5185(m) | 0 | <1 | --- | --- |
| Magnesium | ppm | ASTM D5185(m) | 1010 | 893 | --- | --- |
| Calcium | ppm | ASTM D5185(m) | 1070 | 1169 | --- | --- |
| Phosphorus | ppm | ASTM D5185(m) | 1150 | 904 | --- | --- |
| Zinc | ppm | ASTM D5185(m) | 1270 | 1159 | --- | --- |
| Sulfur | ppm | ASTM D5185(m) | 2060 | 2317 | --- | --- |
| Oxidation | Abs/.1mm | ASTM D7414* | >25 | 21.7 | --- | --- |
| Visc @ 100°C | cSt | ASTM D7279(m) | 15.4 | 13.3 | --- | --- |

Glycol Contamination




Viscosity @ 100°C


Iron (ppm)




Lead (ppm)




Aluminum (ppm)




Chromium (ppm)




Copper (ppm)




Silicon (ppm)




Viscosity @ 100°C




Soot %




ISO 17025:2017 Accredited Laboratory

**Laboratory** : WearCheck - C8-1175 Appleby Line, Burlington, ON L7L 5H9
**Sample No.** : GFL0059106
**Lab Number** : 02619495
**Unique Number** : 5736605
**Test Package** : MOB 1 ( Additional Tests: Glycol )

**Received** : 04 Mar 2024
**Tested** : 04 Mar 2024
**Diagnosed** : 04 Mar 2024 - Wes Davis

*To discuss this sample report, contact Customer Service at 1-800-268-2131.*
*Test denoted (*) outside scope of accreditation, (m) method modified, (e) tested at external lab.*
*Validity of results and interpretation are based on the sample and information as supplied.*

**GFL Environmental - 570 - Thunder Bay**
3000 Highway 61,
Slate River, ON
CA P7J 0G8
Contact: Cindy Wall
cwall@gflenv.com
T: (807)577-0411
F: