FLEET LUBE 360 OIL DIAGNOSTICS

# OIL ANALYSIS REPORT

| | |
|---|---|
| WEAR | NORMAL |
| CONTAMINATION | SEVERE |
| FLUID CONDITION | ABNORMAL |

Machine Id
**723022-361626**
Component
**Diesel Engine**
Fluid
**PETRO CANADA DURON SHP 15W40 (--- GAL)**

## RECOMMENDATION

We advise that you check the fuel injection system. Oil and filter change at the time of sampling has been noted. We recommend an early resample to monitor this condition.

## WEAR

All component wear rates are normal.

## CONTAMINATION

There is a high amount of fuel present in the oil.

## FLUID CONDITION

Fuel is present in the oil and is lowering the viscosity. The BN result indicates that there is suitable alkalinity remaining in the oil. The oil is no longer serviceable due to the presence of contaminants.

| Test | UOM | Method | Limit/Abn | Current | History1 | History2 |
|---|---|---|---|---|---|---|
| Sample Number | | Client Info | | **GFL0092122** | GFL0092088 | GFL0084674 |
| Sample Date | | Client Info | | **06 Feb 2024** | 02 Dec 2023 | 07 Jun 2023 |
| Machine Age | hrs | Client Info | | **18953** | 233406 | 233406 |
| Oil Age | hrs | Client Info | | **600** | 228171 | 0 |
| Filter Age | hrs | Client Info | | **600** | 0 | 0 |
| Oil Changed | | Client Info | | **Changed** | Not Changd | Not Changd |
| Filter Changed | | Client Info | | **Changed** | Not Changd | Not Changd |
| Sample Status | | | | **SEVERE** | ABNORMAL | NORMAL |
| Iron | ppm | ASTM D5185m | >80 | **84** | 66 | 33 |
| Chromium | ppm | ASTM D5185m | >5 | **3** | 3 | 1 |
| Nickel | ppm | ASTM D5185m | >2 | **<1** | 0 | <1 |
| Titanium | ppm | ASTM D5185m | | **<1** | 0 | 0 |
| Silver | ppm | ASTM D5185m | >3 | **0** | 0 | 0 |
| Aluminum | ppm | ASTM D5185m | >30 | **7** | 5 | 4 |
| Lead | ppm | ASTM D5185m | >30 | **3** | 2 | 0 |
| Copper | ppm | ASTM D5185m | >150 | **5** | 7 | 2 |
| Tin | ppm | ASTM D5185m | >5 | **2** | <1 | <1 |
| Vanadium | ppm | ASTM D5185m | | **<1** | 0 | 0 |
| White Metal | scalar | *Visual | NONE | **NONE** | NONE | NONE |
| Yellow Metal | scalar | *Visual | NONE | **NONE** | NONE | NONE |
| Silicon | ppm | ASTM D5185m | >20 | **14** | 13 | 9 |
| Potassium | ppm | ASTM D5185m | >20 | **0** | 4 | 4 |
| Fuel | % | ASTM D3524 | >5 | **16.8** | <1.0 | <1.0 |
| Water | | WC Method | >0.2 | **NEG** | NEG | NEG |
| Glycol | | WC Method | | **NEG** | NEG | NEG |
| Soot % | % | *ASTM D7844 | >3 | **1.5** | 4.2 | 2.4 |
| Nitration | Abs/cm | *ASTM D7624 | >20 | **16.0** | 16.1 | 12.4 |
| Sulfation | Abs/.1mm | *ASTM D7415 | >30 | **27.6** | 30.0 | 25.1 |
| Silt | scalar | *Visual | NONE | **NONE** | NONE | NONE |
| Debris | scalar | *Visual | NONE | **NONE** | NONE | NONE |
| Sand/Dirt | scalar | *Visual | NONE | **NONE** | NONE | NONE |
| Appearance | scalar | *Visual | NORML | **NORML** | NORML | NORML |
| Odor | scalar | *Visual | NORML | **NORML** | NORML | NORML |
| Emulsified Water | scalar | *Visual | >0.2 | **NEG** | NEG | NEG |
| Sodium | ppm | ASTM D5185m | | **11** | 11 | 59 |
| Boron | ppm | ASTM D5185m | 0 | **10** | 1 | 4 |
| Barium | ppm | ASTM D5185m | 0 | **0** | 2 | 0 |
| Molybdenum | ppm | ASTM D5185m | 60 | **45** | 56 | 59 |
| Manganese | ppm | ASTM D5185m | 0 | **<1** | 0 | <1 |
| Magnesium | ppm | ASTM D5185m | 1010 | **637** | 826 | 954 |
| Calcium | ppm | ASTM D5185m | 1070 | **995** | 1014 | 1114 |
| Phosphorus | ppm | ASTM D5185m | 1150 | **727** | 871 | 1014 |
| Zinc | ppm | ASTM D5185m | 1270 | **911** | 1090 | 1238 |
| Sulfur | ppm | ASTM D5185m | 2060 | **1980** | 2589 | 3437 |
| Oxidation | Abs/.1mm | *ASTM D7414 | >25 | **33.1** | 23.7 | 21.6 |
| Base Number (BN) | mg KOH/g | ASTM D2896 | 9.8 | **4.8** | 4.4 | 8.6 |
| Visc @ 100°C | cSt | ASTM D445 | 15.4 | **10.1** | 14.2 | 14.1 |

Fuel Dilution




Viscosity @ 100°C




Base Number




Ferrous Alloys




Non-ferrous Metals




Viscosity @ 100°C




Base Number




Certificate L2367

**Laboratory** : WearCheck USA - 501 Madison Ave., Cary, NC 27513
**Sample No.** : GFL0092122
**Lab Number** : 06084275
**Unique Number** : 10871720
**Test Package** : FLEET ( Additional Tests: FuelDilution, PercentFuel )

**Received** : 08 Feb 2024
**Tested** : 13 Feb 2024
**Diagnosed** : 13 Feb 2024 - Jonathan Hester

*To discuss this sample report, contact Customer Service at 1-800-237-1369.*
** - Denotes test methods that are outside of the ISO 17025 scope of accreditation.*
*Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012)*

**GFL Environmental - 856 - Houston South**
8515 Highway 6 South
Houston, TX
US 77083
Contact: Apolinar Zacarias
pzacariascano@gflenv.com
T:
F: