FLEET LUBE 360 OIL DIAGNOSTICS

# OIL ANALYSIS REPORT

| | |
|---|---|
| WEAR | NORMAL |
| CONTAMINATION | NORMAL |
| FLUID CONDITION | NORMAL |

Area
**(YA130696)**
Machine Id
**10417C**
Component
**Natural Gas Engine**
Fluid
**CHEVRON DELO 400 NG (30 GAL)**

## RECOMMENDATION

Resample at the next service interval to monitor.

## WEAR

All component wear rates are normal.

## CONTAMINATION

There is no indication of any contamination in the oil.

## FLUID CONDITION

The BN result indicates that there is suitable alkalinity remaining in the oil. The condition of the oil is suitable for further service.

| Test | UOM | Method | Limit/Abn | Current | History1 | History2 |
|---|---|---|---|---|---|---|
| Sample Number | | Client Info | | GFL0123412 | GFL0082461 | GFL0050797 |
| Sample Date | | Client Info | | 18 Jun 2024 | 17 Jul 2023 | 06 Feb 2023 |
| Machine Age | hrs | Client Info | | 95952 | 6505 | 5278 |
| Oil Age | hrs | Client Info | | 95952 | 1227 | 1180 |
| Filter Age | hrs | Client Info | | 0 | 1227 | 1180 |
| Oil Changed | | Client Info | | N/A | Changed | Changed |
| Filter Changed | | Client Info | | N/A | Changed | Changed |
| Sample Status | | | | NORMAL | NORMAL | ABNORMAL |
| Iron | ppm | ASTM D5185m | >50 | 4 | 13 | 26 |
| Chromium | ppm | ASTM D5185m | >4 | <1 | 2 | ▲ 6 |
| Nickel | ppm | ASTM D5185m | >2 | 0 | 0 | 0 |
| Titanium | ppm | ASTM D5185m | | <1 | 0 | 0 |
| Silver | ppm | ASTM D5185m | >3 | 0 | 0 | 0 |
| Aluminum | ppm | ASTM D5185m | >9 | 1 | 2 | 3 |
| Lead | ppm | ASTM D5185m | >30 | 2 | 9 | 2 |
| Copper | ppm | ASTM D5185m | >35 | <1 | 1 | 1 |
| Tin | ppm | ASTM D5185m | >4 | 0 | 0 | <1 |
| Vanadium | ppm | ASTM D5185m | | <1 | 0 | 0 |
| White Metal | scalar | *Visual | NONE | NONE | NONE | NONE |
| Yellow Metal | scalar | *Visual | NONE | NONE | NONE | NONE |
| Silicon | ppm | ASTM D5185m | >+100 | 3 | 5 | 0 |
| Potassium | ppm | ASTM D5185m | >20 | 2 | 16 | 8 |
| Water | | WC Method | >0.1 | NEG | NEG | NEG |
| Soot % | % | *ASTM D7844 | | 0 | 0 | 0.1 |
| Nitration | Abs/cm | *ASTM D7624 | >20 | 6.7 | 10.7 | 12.9 |
| Sulfation | Abs/.1mm | *ASTM D7415 | >30 | 19.1 | 23.4 | 25.8 |
| Silt | scalar | *Visual | NONE | NONE | NONE | NONE |
| Debris | scalar | *Visual | NONE | NONE | NONE | NONE |
| Sand/Dirt | scalar | *Visual | NONE | NONE | NONE | NONE |
| Appearance | scalar | *Visual | NORML | NORML | NORML | NORML |
| Odor | scalar | *Visual | NORML | NORML | NORML | NORML |
| Emulsified Water | scalar | *Visual | >0.1 | NEG | NEG | NEG |
| Sodium | ppm | ASTM D5185m | | 4 | 10 | 13 |
| Boron | ppm | ASTM D5185m | | 43 | 0 | 11 |
| Barium | ppm | ASTM D5185m | | 0 | 0 | 0 |
| Molybdenum | ppm | ASTM D5185m | | 51 | 62 | 79 |
| Manganese | ppm | ASTM D5185m | | <1 | 1 | <1 |
| Magnesium | ppm | ASTM D5185m | | 640 | 677 | 721 |
| Calcium | ppm | ASTM D5185m | | 1780 | 1987 | 2349 |
| Phosphorus | ppm | ASTM D5185m | 800 | 918 | 899 | 1003 |
| Zinc | ppm | ASTM D5185m | 880 | 1108 | 1172 | 1254 |
| Sulfur | ppm | ASTM D5185m | | 3365 | 3315 | 2730 |
| Oxidation | Abs/.1mm | *ASTM D7414 | >25 | 15.7 | 18.7 | 18.6 |
| Base Number (BN) | mg KOH/g | ASTM D2896 | 6.1 | 8.1 | 6.6 | 6.2 |
| Visc @ 100°C | cSt | ASTM D445 | 15.8 | 14.3 | 15.0 | 14.7 |

FT-IR (Direct Trend)




Base Number




Viscosity @ 100°C




Ferrous Alloys




Non-ferrous Metals




Viscosity @ 100°C




Base Number




Certificate L2367

**Laboratory** : WearCheck USA - 501 Madison Ave., Cary, NC 27513
**Sample No.** : GFL0123412
**Lab Number** : 06215564
**Unique Number** : 11088428
**Test Package** : FLEET

**Received** : 20 Jun 2024
**Tested** : 21 Jun 2024
**Diagnosed** : 21 Jun 2024 - Wes Davis

*To discuss this sample report, contact Customer Service at 1-800-237-1369.*
** - Denotes test methods that are outside of the ISO 17025 scope of accreditation.*
*Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012)*

**GFL Environmental - 007 - Brunswick**
2809 Galloway Road
Bolivia, NC
US 28422
Contact: DONALD CRAVEN
dcraven@gflenv.com
T:
F: (910)253-4179