OIL ANALYSIS REPORT

Sample Rating Trend



NORMAL

Machine Id
722002
Component
Diesel Engine
Fluid
PETRO CANADA DURON SHP 15W40 (--- GAL)

DIAGNOSIS

Recommendation
No corrective action is recommended at this time. Resample at the next service interval to monitor.

Wear
All component wear rates are normal.

Contamination
Light fuel dilution occurring. No other contaminants were detected in the oil.

Fluid Condition
The condition of the oil is acceptable for the time in service.

SAMPLE INFORMATION		method	limit/base	current	history1	history2
Sample Number		Client Info		**GFL0053572**	GFL0090865	GFL0078496
Sample Date		Client Info		**27 Sep 2023**	22 Sep 2023	18 Jul 2023
Machine Age	hrs	Client Info		**0**	0	26704
Oil Age	hrs	Client Info		**27131**	27095	0
Oil Changed		Client Info		**N/A**	N/A	N/A
Sample Status				**NORMAL**	ABNORMAL	SEVERE

CONTAMINATION		method	limit/base	current	history1	history2
Glycol		WC Method		**NEG**	NEG	NEG

WEAR METALS		method	limit/base	current	history1	history2
Iron	ppm	ASTM D5185(m)	>120	**7**	8	29
Chromium	ppm	ASTM D5185(m)	>20	**0**	0	<1
Nickel	ppm	ASTM D5185(m)	>5	**0**	<1	<1
Titanium	ppm	ASTM D5185(m)	>2	**0**	0	1
Silver	ppm	ASTM D5185(m)	>2	**<1**	<1	<1
Aluminum	ppm	ASTM D5185(m)	>20	**1**	2	13
Lead	ppm	ASTM D5185(m)	>40	**<1**	<1	<1
Copper	ppm	ASTM D5185(m)	>330	**<1**	2	3
Tin	ppm	ASTM D5185(m)	>15	**0**	0	<1
Antimony	ppm	ASTM D5185(m)		**0**	0	0
Vanadium	ppm	ASTM D5185(m)		**0**	0	0
Beryllium	ppm	ASTM D5185(m)		**0**	0	0
Cadmium	ppm	ASTM D5185(m)		**0**	0	0

ADDITIVES		method	limit/base	current	history1	history2
Boron	ppm	ASTM D5185(m)	0	**8**	28	40
Barium	ppm	ASTM D5185(m)	0	**<1**	0	0
Molybdenum	ppm	ASTM D5185(m)	60	**57**	46	24
Manganese	ppm	ASTM D5185(m)	0	**0**	0	<1
Magnesium	ppm	ASTM D5185(m)	1010	**909**	682	319
Calcium	ppm	ASTM D5185(m)	1070	**1070**	1271	1835
Phosphorus	ppm	ASTM D5185(m)	1150	**959**	839	850
Zinc	ppm	ASTM D5185(m)	1270	**1130**	994	953
Sulfur	ppm	ASTM D5185(m)	2060	**2504**	2273	2412
Lithium	ppm	ASTM D5185(m)		**<1**	<1	<1

CONTAMINANTS		method	limit/base	current	history1	history2
Silicon	ppm	ASTM D5185(m)	>25	**7**	4	6
Sodium	ppm	ASTM D5185(m)		**3**	3	5
Potassium	ppm	ASTM D5185(m)	>20	**1**	3	32
Fuel	%	ASTM D7593*	>3.0	**1.1**	▲ 4.1	⬢ 5.2

INFRA-RED		method	limit/base	current	history1	history2
Soot %	%	ASTM D7844*	>4	**0**	0.4	0.2
Nitration	Abs/cm	ASTM D7624*	>20	**5.7**	6.2	9.4
Sulfation	Abs/.1mm	ASTM D7415*	>30	**18.1**	19.8	21.9

FLUID DEGRADATION		method	limit/base	current	history1	history2
Oxidation	Abs/.1mm	ASTM D7414*	>25	**14.2**	15.5	19.0

OIL ANALYSIS REPORT

Fuel Dilution



Viscosity @ 100°C



VISUAL		method	limit/base	current	history1	history2
Emulsified Water	scalar	Visual*	>0.2	**NEG**	NEG	NEG
Free Water	scalar	Visual*		**NEG**	NEG	NEG

FLUID PROPERTIES		method	limit/base	current	history1	history2
Visc @ 100°C	cSt	ASTM D7279(m)	15.4	**13.6**	▲ 11.8	⬢ 10.6

GRAPHS

Iron (ppm)



Lead (ppm)



Aluminum (ppm)



Chromium (ppm)



Copper (ppm)



Silicon (ppm)



Viscosity @ 100°C



Soot %



CALA
ISO 17025:2017 Accredited Laboratory

Laboratory : WearCheck - C8-1175 Appleby Line, Burlington, ON L7L 5H9
Sample No. : GFL0053572
Lab Number : 02585731
Unique Number : 5646796
Test Package : MOB 1 (Additional Tests: PercentFuel)

Received : 28 Sep 2023
Diagnosed : 02 Oct 2023
Diagnostician : Wes Davis

To discuss this sample report, contact Customer Service at 1-800-268-2131.
Test denoted (*) outside scope of accreditation, (m) method modified, (e) tested at external lab.
Validity of results and interpretation are based on the sample and information as supplied.

GFL Environmental - 246 - Windsor
2700 Deziel Dr
Windsor, ON
CA N8W 5H8
Contact: Dave Varga
dvarga@gflenv.com
T: (519)944-8009
F: