OIL ANALYSIS REPORT

Sample Rating Trend



FUEL

Machine Id
8138
Component
Diesel Engine
Fluid
PETRO CANADA DURON SHP 10W30 (--- GAL)

DIAGNOSIS

Recommendation
We recommend that you drain the oil from the component if this has not already been done. We recommend an early resample to monitor this condition.

Wear
All component wear rates are normal.

Contamination
There is a moderate amount of fuel present in the oil. Tests confirm the presence of fuel in the oil.

Fluid Condition
Fuel is present in the oil and is lowering the viscosity. The oil is no longer serviceable due to the presence of contaminants.

SAMPLE INFORMATION		method	limit/base	current	history1	history2
Sample Number		Client Info		**GFL0093876**	GFL0097643	GFL0085931
Sample Date		Client Info		**29 Oct 2023**	12 Oct 2023	06 Jul 2023
Machine Age	hrs	Client Info		**16955**	16893	16324
Oil Age	hrs	Client Info		**0**	0	0
Oil Changed		Client Info		**N/A**	Changed	N/A
Sample Status				**ABNORMAL**	SEVERE	SEVERE

CONTAMINATION	method	limit/base	current	history1	history2
Glycol	WC Method		**NEG**	NEG	NEG

WEAR METALS		method	limit/base	current	history1	history2
Iron	ppm	ASTM D5185(m)	>80	**14**	42	39
Chromium	ppm	ASTM D5185(m)	>5	**<1**	2	2
Nickel	ppm	ASTM D5185(m)	>2	**<1**	<1	<1
Titanium	ppm	ASTM D5185(m)		**0**	0	0
Silver	ppm	ASTM D5185(m)	>3	**<1**	<1	<1
Aluminum	ppm	ASTM D5185(m)	>30	**<1**	1	1
Lead	ppm	ASTM D5185(m)	>30	**3**	15	9
Copper	ppm	ASTM D5185(m)	>150	**<1**	2	1
Tin	ppm	ASTM D5185(m)	>5	**<1**	<1	1
Antimony	ppm	ASTM D5185(m)		**0**	0	<1
Vanadium	ppm	ASTM D5185(m)		**0**	0	0
Beryllium	ppm	ASTM D5185(m)		**0**	0	0
Cadmium	ppm	ASTM D5185(m)		**0**	0	0

ADDITIVES		method	limit/base	current	history1	history2
Boron	ppm	ASTM D5185(m)	2	**7**	2	2
Barium	ppm	ASTM D5185(m)	0	**<1**	<1	0
Molybdenum	ppm	ASTM D5185(m)	50	**53**	45	43
Manganese	ppm	ASTM D5185(m)	0	**0**	0	<1
Magnesium	ppm	ASTM D5185(m)	950	**833**	711	699
Calcium	ppm	ASTM D5185(m)	1050	**931**	774	742
Phosphorus	ppm	ASTM D5185(m)	995	**888**	736	759
Zinc	ppm	ASTM D5185(m)	1180	**1034**	884	869
Sulfur	ppm	ASTM D5185(m)	2600	**2273**	1834	1786
Lithium	ppm	ASTM D5185(m)		**<1**	<1	<1

CONTAMINANTS		method	limit/base	current	history1	history2
Silicon	ppm	ASTM D5185(m)	>20	**3**	5	5
Sodium	ppm	ASTM D5185(m)		**4**	9	7
Potassium	ppm	ASTM D5185(m)	>20	**0**	<1	1
Fuel	%	ASTM D7593*	>5	▲ **7.2**	⬢ 13	⬢ 18.9

INFRA-RED		method	limit/base	current	history1	history2
Soot %	%	ASTM D7844*	>3	**0.4**	0.9	0.9
Nitration	Abs/cm	ASTM D7624*	>20	**7.4**	12.0	11.3
Sulfation	Abs/.1mm	ASTM D7415*	>30	**20.4**	29.0	27.6

FLUID DEGRADATION		method	limit/base	current	history1	history2
Oxidation	Abs/.1mm	ASTM D7414*	>25	**17.9**	36.2	33.3

OIL ANALYSIS REPORT

VISUAL		method	limit/base	current	history1	history2
Emulsified Water	scalar	Visual*	>0.2	**NEG**	NEG	NEG
Free Water	scalar	Visual*		**NEG**	NEG	NEG

FLUID PROPERTIES		method	limit/base	current	history1	history2
Visc @ 100°C	cSt	ASTM D7279(m)	12.00	▲ **9.9**	▲ 8.5	⬢ 7.6

GRAPHS

Fuel Dilution



Viscosity @ 100°C



Iron (ppm)



Lead (ppm)



Aluminum (ppm)



Chromium (ppm)



Copper (ppm)



Silicon (ppm)



Viscosity @ 100°C



Fuel Dilution



ISO 17025:2017 Accredited Laboratory

Laboratory : WearCheck - C8-1175 Appleby Line, Burlington, ON L7L 5H9 **GFL Environmental - 554 - Edmonton SW**
Sample No. : GFL0093876 **Received** : 30 Oct 2023
Lab Number : 02592536 **Diagnosed** : 31 Oct 2023
Unique Number : 5669615 **Diagnostician** : Wes Davis
Test Package : MOB 1 (Additional Tests: PercentFuel)

8409 -15th Street NW
Edmonton, AB
CA T6P 0B8
Contact: Tim Greig
tgreig@gflenv.com
T: (780)231-0521
F:

To discuss this sample report, contact Customer Service at 1-800-268-2131.
Test denoted (*) outside scope of accreditation, (m) method modified, (e) tested at external lab.
Validity of results and interpretation are based on the sample and information as supplied.